



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

December 14, 2007

MR. BRYAN ATKINSON
SERVICE DIRECTOR
WEEKEND WARRIOR TRAILERS, INC.
1320 OLEANDER AVENUE
PERRIS, CA 92571

NVS-215paw
07V-560

Subject: FUEL TRANSFER PUMP LEAK/GPI

Dear MR. ATKINSON:

This letter serves to acknowledge Weekend Warrior Trailers, Inc.'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety defect in the products described below, for which a safety recall campaign shall be conducted pursuant to 49 U.S.C. § 30119.

Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

WEEKEND WARRIOR/CL/2007
WEEKEND WARRIOR/CR/2007
WEEKEND WARRIOR/FB/2007
WEEKEND WARRIOR/FS/2007
WEEKEND WARRIOR/FSC/2007
WEEKEND WARRIOR/LE/2007

NHTSA Campaign Number: 07V-560

Mfg's Report Date: November 26, 2007

Components: FUEL SYSTEM, GASOLINE:DELIVERY:FUEL PUMP

Potential Number of Units Affected: 289

Summary:

ON CERTAIN TOY HAULER RECREATIONAL TRAILERS EQUIPPED WITH GREAT PLAINS INDUSTRIES (GPI) FUEL TRANSFER PUMPS, DUE TO INSUFFICIENT EPOXY ADHESIVE APPLIED AT THE TIME OF INSTALLATION AT THE FACTORY, A FUEL LEAK CAN OCCUR AT THE PUMP'S INLET VALVE.

Consequence:

IN THE PRESENCE OF AN IGNITION SOURCE, A FIRE CAN OCCUR.

Remedy:

GPI HAS REPLACED ALL THE FUEL PUMPS INVOLVED IN THE RECALL.

Notes:

CUSTOMERS MAY ALSO CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION'S VEHICLE SAFETY HOTLINE AT 1-888-327-4236 (TTY 1-800-424-9153), OR GO TO [HTTP://WWW.SAFERCAR.GOV](http://www.safercar.gov).

This recall was the subject of an Equipment Query, EQ06-016, conducted by the Office of Defects Investigation.

The information in your defect report appears to satisfy the requirements of 49 CFR 573.6.

Please provide the following additional information and be reminded of the following requirements:

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in your report, all fuel pumps have been replaced by GPI. No further reports are required.

Your contacts for this recall will be Pat Wallace or Delia Lopez, who may be reached by phone at 202-366-5232 or 202-366-9525 or by email at Patricia.wallace@dot.gov, Delia.lopez@dot.gov, or through the office email at RMD.ODI@dot.gov. We look forward to working with you for successful completion of this recall campaign.

Sincerely,

A handwritten signature in black ink, appearing to read "G. Person".

George H. Person
Chief, Recall Management Division
Office of Defects Investigation
Enforcement