



March 5, 2007



Mr Daniel C. Smith  
Associate Administrator for Enforcement  
National Highway Traffic Safety Administration  
400 Seventh Street, SW  
Washington, DC 20590

07V-119  
(3 pages)

RE: Defect Information Report; Vehicles Equipped with  
Certain Refrigerators Manufactured by Dometic Corporation

Dear Valued Customer:

Coach House Inc. has been advised by Dometic Corporation that certain Dometic refrigerators installed as original equipment in some of Coach House Inc's recreational vehicles may contain a defect that relates to motor vehicle safety. Because they may experience a leak of pressurized coolant solution which can result in a vehicle fire under certain specific circumstances.. On the basis of that Dometic determination, Coach House Inc has decided that there may be a potential safety defect in its vehicles equipped with the identified refrigerators, and we are therefore submitting the enclosed Defect Information Report pursuant to 49 CFR Part 573.

If you have any questions, please do not hesitate to contact the undersigned at 800-235-0984.

Sincerely,

Steve Gerzeny  
Vice President

Enclosure

RECEIVED  
2007 MAR 20 A 9:53  
COACH HOUSE INC



*Coach House,® Inc.*



DEFECT INFORMATION REPORT

1. Manufacturer's name/address:

The manufacturer of the vehicles covered by this Report is:

Coach House Inc  
3480 Technology Drive  
Nokomis, FL 34275  
800-235-0984

2. Vehicles Involved:

The vehicles covered by this Report are recreational vehicles that are equipped with certain models of refrigerators manufactured by Dometic Corporation between April 1997 and May 2003. The vehicle models in questions are as follows: Coach House Class B and Coach House Platinum.

3. Total number of vehicles:

The total number of vehicles covered by this Report is 621.

4. Approximate percentage of vehicles estimated to actually contain the defect:

Coach House does not know how many of their coach's will contain a defective refrigerator.

5. Description of the defect:

Under some circumstances, a fatigue crack can develop in the boiler tube of the Covered refrigerators, which can permit the release of pressurized coolant solution. If this solution is exposed to a ignition source under certain specific circumstances, it can result in a vehicle fire.

6. Chronological summary of events leading to this determination:

Dometic advised Coach House of its defect determination by letter, Coach House Inc. is not aware of any fires in its vehicles that appear to be related to this defect. Nevertheless, after reviewing the matter, Coach House Inc decided to submit this defect report.




*Coach House,® Inc.*



7. Program for remedying the defect:

Dometic has arranged to conduct a recall to remedy the potential defect in Coach House Inc's vehicles at no charge to vehicle owners. See Recall No. 06E-076. Pursuant to 49 CFR 573.6(c)(8)(i) and 573.13, owners will be advised that Dometic will reimburse them if they have incurred costs to obtain a remedy for a refrigerator containing such a defect prior to their receipt of the notification.

  
Steve Gerzenv  
Vice-President