

TL INDUSTRIES, INC.  
25876 MINER ROAD  
ELKHART, IN. 46514  
PHONE (574) 264-3127  
FAX (574) 264-0131

07V-166  
(2 oages)

March 20, 2007

Mr. Daniel C. Smith  
Associated Administrator for Enforcement  
National Highway Traffic Safety Administration  
400 Seventh Street, SW  
Washington, DC 20590

Re: Defect Information Report; Vehicles Equipped with  
Certain Refrigerators Manufactured by Dometic Corporation


Dear Mr. Smith:

TL Industries, Inc. has been advised by Dometic Corporation that certain Dometic Corporation that certain Dometic refrigerators installed as original equipment In some of TL Industries, Inc. recreational vehicles may contain a defect that relates to To motor vehicle safety because they may experience a leak of pressurized coolant solution which can result in a vehicle fire under certain specific circumstances. On the basis of that Dometic determination, TL Industries, has decided that there may be a potential safety defect in its vehicles equipped with the identified refrigerators, and we are therefore submitting the enclosed Defect Information Report pursuant to 49 CFR Part 573.

If you have any questions, please to do not hesitate to contact the undersigned at 574-264-3127.

Sincerely,

Barb Keller



RECEIVED

2007 APR 16 A 10:30

DEFECTS INVESTIGATION  
RECALL MGMT DIV.

TL INDUSTRIES, INC.

1. Manufacturer's name/address:

The manufacturer of the vehicles covered by this report is :  
TL INDUSTRIES, INC.  
25876 MINER ROAD  
ELKHART INDIANA 46514

2. Vehicles Involved:

The vehicles covered by this report are recreational vehicles that were equipped with Certain model of refrigerators manufactured by Dometic Corporation between April 1997 and May 2003. TL Industries started using Dometic Corporation March of 1999.

3. Total number vehicles:

Total number of vehicles covered 653

4. Approximate percentage of vehicles estimated to actually contain the defect:

Based on information received from Dometic, believes that approximately .06 percent of these vehicles actually contain the defect.

5. Under some circumstances, a fatigue crack can develop in the boiler tube of the Covered refrigerators, which can permit the release of pressurized coolant solution. If this solution is exposed to an ignition source under certain specific circumstances, It can result in a vehicle fire.

6. Chronological summary of events leading to this determination:

Dometic advised TL INDUSTRIES, of the defect determination. TL will submit this report. We know of 0 defects.

7. Program for remedying the defect:

Dometic has arranged to conduct a recall to remedy the potential defect in TL INDUSTRIES vehicles at no charge to vehicle owners. See Recall No. .06E-076. Pursuant to 49 CFR 573f.6 (c) (8)(i) and 573.13, owners will be advised that Dometic will reimburse them if they have incurred costs to obtain a remedy for a refrigerator containing such a defect prior to their receipt of the notification.

Barb Keller  
General Manager