



RECEIVED

2007 FEB 13 A 8:50

OFFICE OF DEFECTS  
INVESTIGATION

## NOTIFICATION OF RECALL

February 12, 2007

Mr. James Eledge  
Manager Warranty Operations  
Gulf States Toyota, Inc.  
7701 Wilshire Place Drive  
Houston, TX 77040

Dear Mr. Eledge:

This notice is sent to you in accordance with the requirements of the National Highway Traffic and Motor Vehicle Safety Act.

Rostra Precision Controls, Inc. ("Rostra") has determined that a defect which relates to motor vehicle safety exists in certain cruise control units manufactured by Rostra, for installation in 2006 and 2007 Toyota Scion, Models xA and xB. These units were manufactured between September 1, 2006 and January 15, 2007. A quantity of those units has been sold to you and some of those units have been installed in vehicles.

What is the problem?

On occasion, while the cruise control is engaged, if the cruise control "On/Off" switch is pressed once, the throttle does not return to idle. When the "On/Off" switch is pressed a second time, the throttle will return to idle.

An accident could be caused in the event that the cruise control does not allow the engine to return to idle on the first depression of the "On/Off" switch.

The safety devices built into the cruise control unit will, however, still disengage the throttle if the driver steps on the brake while the cruise control is still "on".

What should be done?

First, it is imperative that no cruise control units affected by the defect be sold prior to the time that they have been tested and repaired, if necessary. Rostra will accept a return of such units. We will inspect and repair them and return them to you without charge. Alternatively, Rostra offers to repurchase each affected unit from you that contains the safety defect described above.

Next, with respect to units which have already been sold, Rostra recommends that, to correct this condition, a letter should be sent to each owner and lessee of an affected vehicle. The letter should state that a Toyota dealer will check and, if necessary, replace the cruise control unit at no cost to the owner/lessee.



What should you do if you have further questions, or if there are problems?

If you have any further questions, please contact the undersigned.

If Rostra fails or is unable to remedy this defect without charge and within a reasonable time, you may submit a written complaint to the Administrator, National Highway Traffic Safety Administration, 400 Seventh Street, SW, Washington, DC 20590, or call 1-888-DASH-2-DOT (1-888-327-4236). Washington DC residents, use 1-202-366-0123.

Some final words

We regret any inconvenience which this action may cause you. However, we have taken this action in the interest of your safety and continued satisfaction with our products.

Thank you for attention to this important matter.

Rostra Precision Controls, Inc.

A handwritten signature in black ink, appearing to read 'Raymond J. Ford', is written over a printed name and title.

Raymond J. Ford, President