

RECEIVED

[Date]

2007 MAR 26 A 8:53

Mr. Gary McCollum
Purchasing Manager Worldwide Purchasing
GM Service and Parts Operations
6200 Grand Pointe Drive
Grand Blanc, Michigan 48439

OFFICE OF DEFECTS
INVESTIGATION

**Re: Notice of Safety Recall of Fuel Pump Modules
Delphi part numbers MU55 and MU269
NHTSA Recall # 07E-015**

Dear Gary:

Delphi has determined that a defect which affects motor vehicle safety exists in approximately 30 fuel modules shipped 24Oct2006 thru 02Feb2007.

The suspect fuel pump modules are service fuel pump modules sold for use in 1996-1998 Pontiac Grand Am, Pontiac Sunfire, Chevrolet Cavalier, Oldsmobile Achieva and Buick Skylark.

(Note: This recall only pertains to service fuel pump modules and has no application to GM factory-installed fuel pump modules.)

The root cause of the non-conformance is associated with the incorrect assembly of the fuel return and vent tube. The two tube positions were switched when assembled by a supplier of Delphi. The following two scenarios can result from the use of a non-conforming fuel pump module:

- The vehicle will not run correctly (idle rough and/or stall) due to an overly rich fuel blend.
- The vehicle's evaporative emission carbon canister may leak fuel.

Delphi has proactively sorted the inventory of dealers who were shipped product during the suspect time frame.

Please forward a copy of this recall notification to your retail outlets, distributors, and known purchasers within 5 working days of receipt.

Please be aware it is a violation of Federal law for a dealer to deliver a new motor vehicle or any new or used item of motor vehicle equipment covered

by the notification under a sale or lease until the defect or noncompliance is remedied.

Vehicle owners who were sold fuel pump modules during the suspect time frame may visit <http://iam.delphi.com/recall/fpm> or call 1-877-335-7443 to determine if they are impacted by the recall. The recall website will be available after March 30, 2007.

Vehicle owners who are impacted will be directed to have their vehicles inspected at the original source (dealer) and non-conforming fuel pump modules will be replaced at no cost to the owner.

If dealers have questions regarding the conformance of stock or consumer reimbursement, please call customer service at 1-877-463-3574.

Thank you for your cooperation in this manner.

Sincerely,

John P. Kelly
Customer Director – GM OE Service
Delphi Product & Service Solutions