



RECEIVED

2007 APR -14 A 10 22

ST. LOUIS, MO

Mr. George Person  
Chief, Recall **Management** Office  
National Highway Traffic Safety **Adm.**  
400 7th Street, S.W.  
Washington, D.C. 20590

**02** April **2007**

Dear Mr. Person:

The mailing of the Customer and Dealer Notifications for Recall **07V-037** began on 19 March and was completed on 22 March 2007. As required, copies of the final notifications **are** being **faxed** for your files. Original copies are being forwarded to your attention via certified mail.

Please feel free to contact me at 541-**998-3720** x8382 should you **have** any questions.

Sincerely,

Dick Sabath  
Senior Manager, Warranty and Compliance Administration  
Country Coach Inc.

Enclosures (2) Customer Notification, 07V-037  
Dealer Notification, 07V-037

THE WORLD'S FINEST MOTORCOACHES

135 East First Avenue | PO Box 400 | Junction City, OR 97468



VIA: CERTIFIED MAIL, RETURN RECEIPT REQUESTED, AND  
FIRST CLASS MAIL

19 March 2007

**RE: Service Provider Notification of Vehicle Safety Defect  
Federal Recall Campaign 07V-037**

Dear Country Coach Service Provider:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act, CFR 49,573.5 and 573.6.

**DESCRIPTION OF SAFETY DEFECT:**

Country Coach has decided that certain Intrigue motor homes manufactured with the Tuthill 1660 independent front suspension have front air brake hoses that could potentially be chaffed and/or rubbed by the steer axle tires or chassis components under certain conditions.

A motor home being operated with a brake hose rubbing, chaffing **and/or** snagging damage could suffer a sudden loss of braking on a steering wheel if the hose ruptured. The sudden loss of braking could cause the motor home to suddenly pull sharply to one side. If the brake treadle continued to be applied, a low air situation could develop and activate the rear spring brakes resulting in a sudden, unplanned stop. Either of these instances could have the potential to result in a vehicle accident.

**MODELS AFFECTED:**

**Model Year:** 2007 Intrigue motor homes manufactured from July 2006 through November 2006

**VIN Range:** 4U7B8EZ1X71010067 - 4U7B8DZ1071010122

*See attached listing for specific coach numbers included in this recall.*

**REMEDY:**

To correct the condition noted above, Country Coach decided to update the front brake line configuration and routing. This work will be performed at no cost to the consumer. All removed parts must be **destroyed** by such means as to preclude their re-use. The amount of labor required to perform this remedy is not expected to exceed **one (1) hour**.

VEHICLE SAFETY  
DEFECT NOTICE

If the condition is not adequately repaired within a reasonable time, the owner maybe entitled to an identical or reasonably equivalent motor home at no charge or to a refund of the purchase price less a reasonable allowance for depreciation. To avoid having to provide these burdensome solutions, every effort **must** be made to promptly schedule an appointment with owners and to repair their motor homes as soon as possible. You should be aware that owners are instructed to contact the customer **service** department if their dealer does not remedy the condition within three (3) days of the mutually agreed upon service date. Owners are also advised to contact the National Highway Traffic Safety Administration if the condition is not remedied without charge and within a reasonable time (See the enclosed Letter to Country Coach Owners).

Sincerely,



Dick Sabath  
Senior Manager, Compliance Administration  
Country Coach, Inc.

Enclosure; Customer Notification

**CUSTOMER LISTING  
RECALL 07V-037**

Coach #	Model	VIN
12119	MIT-42-OVII-ABCD-07	4U7B8EZ1X71010067
12120	MIT-45-JB-ABCD-07	4U7B8FZ1471010068
12121	MIT-45-JB-ABCD-07	4U7B8FZ1671010069
12122	MIT-42-OVII-ABCD-07	4U7B8EZ1X71010070
12123	MIT-45-JB-ABCD-07	4U7B8FZ1471010071
12124	MIT-42-OVII-ABCD-07	4U7B8EZ1771010074
12125	MIT-45-JB-ABCD-07	4U7B8FZ1171010075
12126	MIT-45-JB-ABCD-07	4U7B8FZ1371010076
12127	MIT-45-JB-ABCD-07	4U7B8FZ1571010077
12128	MIT-45-JB-ABCD-07	4U7B8FZ1771010078
12129	MIT-42-OVII-ABCD-07	4U7B8EZ1671010079
12130	MIT-45-JB-ABCD-07	4U7B8FZ1571010080
12131	MIT-42-OVII-ABCD-07	4U7B8EZ1471010081
12132	MIT-45-JB-ABCD-07	4U7B8FZ1971010082
12133	MIT-45-JB-ABCD-07	4U7B8FZ1071010083
12134	MIT-45-JB-ABCD-07	4U7B8FZ1271010084
12135	MIT-42-OVII-ABCD-07	4U7B8EY1X71010085
12136	MIT-45-JB-ABCD-07	4U7B8FZ1671010086
12137	MIT-42-OVII-ABCD-07	4U7B8EZ1571010087
12138	MIT-45-JB-ABCD-07	4U7B8FZ1X71010088
12139	MIT-42-OVII-ABCD-07	4U7B8EZ1971010089
12140	MIT-45-JB-ABCD-07	4U7B8FZ1871010090
12141	MIT-45-JB-ABCD-07	4U7B8FZ1X71010091
12142	MIT-42-OVII-ABCD-07	4U7B8EZ1971010092
12143	MIT-45-JB-ABCD-07	4U7B8FZ1371010093
12144	MIT-45-JB-ABCD-07	4U7B8FZ1571010094
12145	MIT-45-JB-ABCD-07	4U7B8FZ1771010095
12146	MIT-45-JB-ABCD-07	4U7B8FZ1971010096
12147	MIT-45-JB-ABCD-07	4U7B8FZ1071010097
12148	MIT-42-OVII-ABCD-07	4U7B8EZ1X71010098
12149	MIT-42-OVII-ABCD-07	4U7B8EZ1171010099
12150	MIT-42-OVII-ABCD-07	4U7B8EZ1471010100
12151	MIT-45-JB-ABCD-07	4U7B8FZ1971010101
12152	MIT-45-JB-ABCD-07	4U7B8FZ1071010102
12153	MIT-40-EL-ABCD-07	4U7B8DZ1771010103
12154	MIT-42-OVII-ABCD-07	4U7B8EZ1171010104
12155	MIT-45-JB-ABCD-07	4U7B8FZ1671010105
12156	MIT-42-OVII-ABCD-07	4U7B8EZ1571010106
12157	MIT-45-JB-ABCD-07	4U7B8FZ1X71010107
12158	MIT-45-JB-ABCD-07	4U7B8FZ1171010108
12159	MIT-42-OVII-ABCD-07	4U7B8EZ1071010109
12160	MIT-45-JB-ABCD-07	4U7B8FZ1X71010110
12162	MIT-45-JB-ABCD-07	4U7B8FZ1371010112
12163	MIT-45-JB-ABCD-07	4U7B8FZ1571010113
12164	MIT-45-JB-ABCD-07	4U7B8FZ1771010114
12165	MIT-40-EL-ABCD-07	4U7B8DZ1371010115
12167	MIT-45-JB-ABCD-07	4U7B8FZ1271010117
12169	MIT-42-OVII-ABCD-07	4U7B8EZ1371010119
12170	MIT-40-EL-ACD-07	4U7B8DY1571010120
12171	MIT-45-JB-ABCD-07	4U7B8FZ1471010121
12172	MIT-40-EL-ABCD-07	4U7B8DZ1071010122



VIA: CERTIFIED MAIL, RETURN RECEIPT REQUESTED, AND  
FIRST CLASS MAIL

19 March 2007

**RE: Owner Notification of Vehicle Safety Defect  
Federal Recall Campaign 07V-037**

Dear Country Coach Owner:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act, CFR 49, 573.5 and 573.6.

**DESCRIPTION OF SAFETY DEFECT:**

Country Coach has decided that certain Intrigue motor homes manufactured with the Tuthill 1660 independent front suspension have front air brake hoses that could potentially be chaffed and/or rubbed by the steer axle tires or chassis components under certain conditions.

A motor home being operated with a brake hose rubbing, chaffing and/or snagging damage could suffer a sudden loss of braking on a steering wheel if the hose ruptured. The sudden loss of braking could cause the motor home to suddenly pull sharply to one side. If the brake treadle continued to be applied, a low air situation could develop and activate the rear spring brakes resulting in a sudden, unplanned stop. Either of these instances could have the potential to result in a vehicle accident.

**MODELS AFFECTED:**

Model Year: 2007 Intrigue motor homes manufactured from July 2006 through  
November 2006

**VIN Range:** 4U7B8EZ1X71010067 – 4U7B8DZ1071010122

***See attached listing for specific coach numbers included in this recall.***

**REMEDY:**

To correct the condition noted above, Country Coach decided to update the front brake line configuration and routing. This work will be performed at no cost to the consumer. All removed parts must be destroyed by such means as to preclude their re-use. The amount of labor required to perform this remedy is not expected to exceed **one (1) hour**.

If you had this remedy performed before you received this letter, you may be eligible to **receive** reimbursement for the cost of obtaining a pre-notification remedy of the problem associated with this recall. For more information regarding this recall contact Country Coach Inc. Compliance Administration at **1-800-452-8015**, extension 8382.

THE WORLD'S FINEST MOTORCOACHES

135 East First Avenue | PO Box 400 | Junction City, OR 97448

VEHICLE SAFETY  
RECALL

Please present this letter and the enclosed warranty claim to the dealer/service facility when you take your motor home in to be serviced. The dealer/service facility that does the repairs will need the warranty claim for billing.

If you no longer own this motor home, please complete and return the Vehicle Owner Reply Card in the self-addressed postage paid envelope included in this package. Federal regulations requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days after receipt of the original notification.

If you need assistance in locating your nearest Country Coach dealer, please contact Country Coach's customer service department at 1-800-452-8015. The service department will refer you to a service facility near you. If the dealer/service facility fails to remedy the noncompliance on the agreed upon service date or within three (3) days of the scheduled service date, please contact Country Coach customer service by calling 1-800-452-8015 and ask for the Technical Service Representative handling this recall.

If after contacting both your dealer/service facility and Country Coach you are not able to have the noncompliance remedied within a reasonable time and/or at no cost to you, you may wish to contact the National Highway Traffic Safety Administration:

Administrator  
National Highway Traffic Safety Administration  
400 7th Street, S.W.  
Washington D.C. 40990

Or call the Vehicle Safety Hotline's toll free number at 1-888-327-4236 (TTY: 1-800-424-9153)

Or go to <http://www.safercar.gov>

We are sorry for this inconvenience; however, we have taken this action in the interest of your safety and continued satisfaction with your motor home.

Sincerely,



Dick Sabath  
Senior Manager, Compliance Administration  
Country Coach. LLC

Enclosures (2): Vehicle Reply Card  
Warranty Claim