



KIA MOTORS

Parts Bulletin

No: 1500-0005	Section: 1500 - Cooling System
Model: 2002 MY Sportage	Catalog: EPC
Date: June, 2007	P/N Refer: 0K038 15142, 0K038 15140, 0K038 15140A, 0K048 15140A, 0K038 15142QQK

SAFETY RECALL CAMPAIGN: SPORTAGE COOLING FAN BLADE REPLACEMENT

This bulletin provides information related to a safety recall campaign to replace the Cooling Fan Blade. 2002MY Sportage vehicles produced from 5/15/2001~10/2/2002 may experience fan blade cracking due to the heating and cooling of the plastic materials used for the fan blade. During normal engine operation the centrifugal force generated by the fan rotation can cause cracks and fan blade separation from the hub. Kia is replacing the fan blade with a version manufactured with improved material characteristics.

Campaign Part Number Information

DESCRIPTION	PART NUMBER
Fan Blade	0K038 15142QQK
**Campaign Completion Sticker	US020 SC070



*NOTICE

During the week of June 4th, Kia dealers will receive an automatic shipment of part number 0K038 15142QQK to support immediate needs to service vehicles affected by this service campaign. Dealers will receive 2 pieces to support incoming customer repairs. Additional parts can be ordered via Kia's DCS.

Initial dealer shipments will be processed and shipped with stock orders. Some dealers may receive parts in advance of the Technical Service Bulletin (TSB Campaign 070). Please wait for receipt of TSB and related documents prior to beginning vehicle repairs.

*WARNING

CAMPAIGN PARTS ARE NON-RETURNABLE. Please place your parts orders according to actual customer demand. Parts order quantities will be restricted to ensure adequate inventory availability for all dealers.

**Campaign Completion Labels will be distributed to dealer Service Managers and are available in sheets of 8 from your DPSM or may be ordered via DCS.

If you have any questions, please contact the Parts Hotline at 1-800-542-5611.

Additional copies of this and other Parts Bulletins may be found on www.kdealer.net