

NOTIFICATION OF RECALL

February 13, 2007

Dear Customer:

This notice is sent to you in accordance with the requirements of the National Highway Traffic and Motor Vehicle Safety Act.

Rostra Precision Controls, Inc. has decided that a defect which relates to motor vehicle safety exists in certain cruise control units manufactured from September 1, 2006 to January 15, 2007, sold for use as aftermarket equipment on 2004 through 2007 Toyota Scion Models xA and xB passenger vehicles.

What is the problem?

On occasion, while the cruise control is engaged, if the cruise control "On/Off" switch is pressed once, the throttle does not return to idle. When the "On/Off" switch is pressed a second time, the throttle will return to idle.

An accident could be caused in the event that the cruise control does not allow the engine to return to idle on the first depression of the On/Off" switch.

To avoid risk of accident, do not use the cruise control on your car until it has been checked and, if necessary, replaced.

The safety devices built into the cruise control unit will, however, still disengage the throttle if the driver steps on the brake while the cruise control is still "on".

What will the Manufacturer do?

To correct this condition, we suggest that you return to the place at which your cruise control devise was installed. The installer will check, and if necessary replace, the cruise control unit at no cost to you.

What should you do?

Contact your installer and make an appointment to have your cruise control unit replaced. The installer will obtain the replacement unit from the distributor from which it had purchased the original unit.

The service and required parts as described in this letter will be provided free of charge.

To avoid the risk of accident, do not use the cruise control on your car until it has been checked and, if necessary, replaced. If you do use the cruise control before it has been checked and, if necessary, replaced, please remember that the safety devices built into the cruise control unit will disengage the throttle if the driver steps on the brake while the cruise control unit is still “on”.

If you no longer own the vehicle, please so indicate on the enclosed postage-paid form and provide us with the name and address of the new owner.

How long will it take to do the free service?

The work will take about one half hour to complete. However, additional time may be required depending on how dealer appointments are scheduled and processed.

How should you arrange this service?

Contact your installer as soon as possible to schedule an appointment for the free service.

What should you do if you have further questions, or if there are problems?

If you have any further questions, or if you have a problem obtaining the needed service or repair, please contact either:

- Your local installer; or
- The Manufacturer, Rostra Precision Controls, Inc., at 1-910-291-2529.

If your installer or the Manufacturer fails or is unable to remedy this defect without charge and within a reasonable time, you may submit a written complaint to the Administrator, National Highway Traffic Safety Administration, 400 Seventh Street, SW, Washington, DC 20590, or call the toll free Auto Safety Hot Line at 1-888-327-4236 (TTY: 1-800-424-9153), or go to <http://www.safercar.gov>.

If you are a vehicle lessor, Federal law requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

Some final words

We regret any inconvenience which this action may cause you. However, we have taken this action in the interest of your safety and continued satisfaction with our products.

Thank you for attention to this important matter.