

RECEIVED

Date

2007 APR 25 P 2:51

Company

Customer Name

Customer Street Address

City, State, Zip

OFFICE OF THE ATTORNEY GENERAL  
STATE OF MICHIGAN

**Re: Notice of Safety Recall of Fuel Pressure Regulators  
Delphi part numbers FP10020-11B1, FP10026-11B1 and FP10027-11B1  
NHTSA Recall # 07E-021**

Dear Valued Customer:

Delphi has determined that a defect, which affects motor vehicle safety, exists in approximately 340 fuel pressure regulators shipped 09Jan2007 thru 09Feb2007.

The suspect fuel pressure regulators are sold for use in the aftermarket for the following vehicle applications, which have 2.2L, 3.1L, 3.4L, or 5.7L Engines (VINs 4, 5, M, J, E, X, P – RPOs LN2, LG8, L82, LA1, LQ1, L03, LT1) :

- 1996-2005 Buick Century, Regal, Skylark, Rendezvous
- 1991-2005 Chevrolet Impala, Lumina, Monte Carlo, Venture, Beretta, Corsica, Malibu, Cavalier, S10, Camaro
- 1994-2000 GMC Sonoma
- 1991-2004 Oldsmobile Alero, Cutlass, Silhouette, Achieva, Ciera
- 1991-2005 Pontiac Aztek, Grand Am, Grand Prix, Montana, Trans Port, Sunfire, Firebird

**(Note: This recall only pertains to aftermarket fuel pressure regulators and has no application to GM factory-installed fuel pressure regulators.)**

The non-conformance consists of the fuel pressure regulator missing an o'ring and retainer. The non-conformance will result in fuel leaking from the fuel return line at the fuel pressure regulator interface soon after the vehicle key is advanced to or beyond the 'On' position. Within a few seconds there will be a noticeable fuel leak and a fuel odor.

Delphi has proactively sorted the inventory of distributors that were shipped product during the suspect time frame.

**Please forward a copy of this recall notification to your retail outlets, distributors, and known purchasers within 5 working days of receipt.**

**Please be aware it is a violation of Federal law for a dealer to deliver a new motor vehicle or any new or used item of motor vehicle equipment covered by the notification under a sale or lease until the defect or noncompliance is remedied.**

Vehicle owners who were sold fuel pressure regulators during the suspect time frame may visit <http://iam.delphi.com/recall/upr> or call 1-877-411-8770 to determine if they are impacted by the recall. The recall website will be available after May 30, 2007.

Vehicle owners who are impacted will be directed to have their vehicles inspected at the original source (aftermarket service shop) and non-conforming fuel pressure regulators will be replaced at no cost to the owner.

If distributors have questions regarding the conformance of stock or reimbursement, please call 1-877-411-8770.

Thank you for your cooperation in this manner.

Sincerely,

Norman Young  
Global Sales & Service Director  
Delphi Product & Service Solutions