



## SAFETY RECALL NOTICE

KTM Model: «Model»

3/1/2007

Affected VIN: «Vin»

«PdiFirstName» «PdiLastName»

«PdiAddress1»

«PdiCity», «PdiState» «PdiZip»

Dear KTM Customer,

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. KTM North America has decided that a defect which relates to motor vehicle safety exists on all 2004, 2005 and 2006, 950 Adventure, 950 Adventure S, 950 Supermoto and 950 Super Enduro models.

On affected models, the rear brake may feel spongy or soft when applying the brake which may result in improper rear braking. Subsequently, improper rear braking may lead to an accident which may cause injury or death to the rider or others. The cause of the defect involves the potential for air bubbles to enter into the brake system during motorcycle operation. A newly redesigned rear brake caliper / piston kit and master cylinder incorporated with a new piston seal assembly is required to remedy this defect. All master cylinders will be fitted with a new cap utilizing a newly designed membrane to eliminate any air from being introduced to the master cylinder.

It is mandatory that you discontinue riding your motorcycle until the defect has been repaired. Please contact your Authorized KTM North America Dealer (log onto [www.ktmusa.com](http://www.ktmusa.com) for a complete dealer listing) as soon as possible to arrange an appointment to repair the defect. Instructions for the rear brake repair kits have been sent to every authorized KTM dealer. Please plan on leaving your motorcycle at the dealership for the necessary repairs and allow ample time for scheduling in the service department. Your local KTM dealer will schedule your motorcycle for the necessary repairs and determine the appropriate repairs for your motorcycle model. There will be no charge for the dealer's services. To ensure the highest level of safety, performance, and reliability, it is necessary to have your motorcycle repaired immediately.

If you experience difficulties in scheduling or servicing the required repair from an authorized KTM Dealership please contact KTM North America Customer Relations at (440)985-3553 for assistance. Furthermore, you may contact the National Highway Traffic Safety Administration's Motorcycle Safety hotline at 1-888-327-4236 (TTY 1-800-424-9153) or go to <http://www.safercar.gov> if you are unable to receive the repair within a reasonable period of time and free of charge.

If you have repaired your rear brake caliper or rear brake master cylinder prior to receiving this letter you may be eligible to receive reimbursement for the cost. For reimbursement details contact KTM North America Customer Relations at (440)985-3553 for details.

If you have sold, traded or no longer own this motorcycle it is important for the safety of the current owner that you inform KTM of the current ownership or unknown ownership status by returning the second page of this letter in the enclosed self addressed prepaid postage envelope.

We apologize for any inconvenience and want to assure you that our commitment together with KTM North America Dealers is to provide you with the highest level of service, support and customer satisfaction.

Best Regards,  
Customer Support and Warranty Department  
KTM North America, Inc.

KTM NORTH AMERICA, INC.  
Technical Department

EAST • 1119 Milan Avenue • Amherst • Ohio 44001 • Phone 440-985-3553 • Fax 440-985-3060

WEST • 27635 Diaz Road • Temecula • California 92590 • Phone 951-676-4576

CANADA • 1375-1 Marie-Victorin • Saint-Bruno • Quebec J3V 6B7 • Tél./Phone 450-441-4451 • Fax 450-441-3885

© 2006 KTM North America, Inc. • All rights reserved



**NOTICE:**

If you no longer own this motorcycle please complete the following information of this letter and return to KTM in the enclosed self addressed envelope.

Please complete and return this portion to KTM if ownership of the referenced motorcycle has changed.

**Customer Record Update Form**

The new address is or I have sold the motorcycle to:

New owner's name \_\_\_\_\_

Address \_\_\_\_\_

City, State, Zip \_\_\_\_\_

Phone Number \_\_\_\_\_

«Vin»

«PdiFirstName» «PdiLastName»

«PdiAddress1»

«PdiCity», «PdiState» «PdiZip»

Returning this form will help us to contact the current owner and will enable us to update our records so you can be assured not to receive notifications for this motorcycle in the future.

**KTM NORTH AMERICA, INC.**  
Technical Department

**EAST** » 1119 Milan Avenue » Amherst » Ohio 44001 » Phone 440-985-3553 » Fax 440-985-3060

**WEST** » 27635 Diaz Road » Temecula » California 92590 » Phone 951-676-4576

**CANADA** » 1375-1 Marie-Victorin » Saint-Bruno » Quebec J3V 6B7 » Tél./Phone 450-441-4451 » Fax 450-441-3885

© 2006 KTM North America, Inc. ... All rights reserved