

TEXT OF CUSTOMER LETTER

December 2007

IMPORTANT SAFETY AND EMISSIONS RECALL NOTICE

Dear CBR1000RR Owner:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act and the California Air Resources Board.

What is the reason for this notice?

Honda Motor Co., Ltd. has decided that a defect that is related to both motor vehicle safety and emissions regulations exists in certain 2006-2007 model year CBR1000RR motorcycles. Some 2006-2007 CBR1000RR motorcycles have an improperly welded vent pipe in the bottom of the fuel tank. Due to vibration the improperly welded tanks may crack and drip fuel.

Safety Consequence

In the presence of an ignition source, dripping fuel poses a risk of fire or explosion.

Emissions Consequence

Fuel evaporating into the atmosphere will result in the motorcycle no longer meeting regulations. Your motorcycle may fail a state or local emissions inspection if you do not have this recall repair done.

What should you do?

Please call your authorized Honda motorcycle dealer and make an appointment to have your CBR1000RR inspected. If necessary, a new fuel tank will be installed on your CBR1000RR free of charge. Although the repair will take less than one hour, please plan to leave your CBR1000RR for a day to allow the dealer flexibility in scheduling.

California Owners Only:

After completing the inspection/repair procedure, your dealer will give you a Vehicle Emission Recall – Proof of Correction certificate. Keep this certificate for your records as proof that the emissions recall was completed. Submit the certificate to the DMV only if the DMV requests it. The DMV will not renew your registration until this emissions recall has been completed. Please make sure the dealer completes and gives you the certificate.

Emissions Warranty:

In order to ensure your full protection under the emission warranty provisions, it is recommended that you have your CBR1000RR serviced as soon as possible. Failure to do so could be determined as lack of proper maintenance of your CBR1000RR.

Who to contact if you experience problems.

If you are not satisfied with the service you receive from your Honda dealer, you may write to:

American Honda Motor Co., Inc.
Motorcycle Customer Service
Mail Stop 100-4C-7B
1919 Torrance Blvd.
Torrance, CA 90501-2746
(866) 784-1870

TEXT OF CUSTOMER LETTER

If you believe that American Honda or the dealer has failed or is unable to remedy the safety defect in your vehicle, without charge, within a reasonable period of time (60 days from the date you first contact the dealer for a repair appointment), you may submit a complaint to:

Administrator
National Highway Traffic Safety Administration
1200 New Jersey Ave., SE
Washington, DC 20590

Or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153), or go to <http://www.safercar.gov>.

What to do if you feel this notice is in error.

Our records show that you are the current owner of a 2006-2007 CBR1000RR involved in this campaign. If this is not the case, or the name/address information is not correct, please fill out and return the enclosed, postage-paid Information Change Card. We will then update our records.

If you have questions.

If you have any questions about this notice, or need assistance with locating a Honda dealer, please call Honda Motorcycle Customer Service at (866) 784-1870.

We apologize for any inconvenience this campaign may cause you.

Sincerely,

**American Honda Motor Co., Inc.
Motorcycle Division**

TEXT OF CUSTOMER LETTER

Use this form only if you have previously paid for this repair.

**Request For Reimbursement
2006-2007 CBR1000RR Fuel Tank Replacement**

If you meet the following qualifications, American Honda Motor Co., Inc. will reimburse you for the cost of the fuel tank replacement. No reimbursement will be made for other costs or repairs.

1. The vehicle must be a 2006-2007 CBR1000RR.
2. The repair must have been required due to the failure that is the subject of this recall. Crash damage or other unrelated repairs will not be reimbursed.
- 3. The previous fuel tank replacement must have occurred before 12/17/07.**
4. You must have a repair bill showing itemized parts and labor costs, CBR1000RR model, year, VIN, name, address and phone number of the repair shop, and the date of the repair. There must be verification of payment, such as a copy of a cancelled check, cash receipt, or paid invoice.
5. To qualify for reimbursement, it is not necessary that you still own the affected 2006-2007 CBR1000RR, but you must have been the owner when the fuel tank was replaced. Only the owner at the time of the repair may request reimbursement. Do not request reimbursement for the expenses of any other owner.

IF YOU ARE QUALIFIED FOR REIMBURSEMENT:

Fill in the blanks; please print clearly.

Name: _____

Street Address: _____

City: _____ State: _____ Zip Code: _____

Telephone: _____

Vehicle Identification Number (VIN): _____

Total Amount Requested: _____

Mail this form together with a copy of your repair bill and verification of payment to:

American Honda Motor Co., Inc.
Customer Support, M/S 100-4C-7B
1919 Torrance Blvd.
Torrance, CA 90501-2746

Please allow 6–8 weeks for reimbursement processing.

This form is provided for dealer information and customer photocopies if needed.