

January 9, 2008

Subject: 07KWE – TRW TAS85 Steering Gear
Vin No.

Dear Kenworth Customer,

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Kenworth Truck Company in conjunction with TRW has decided that a defect which relates to motor vehicle safety exists in some C500, T2000, T660 & T800 models manufactured August 23, 2007 through November 19, 2007, with certain TAS85 steering gears. Your vehicle has been identified as possibly having been manufactured with this defect.

TRW notified Kenworth that in certain TAS85 steering gears an incorrect profile on the sector shaft gear may lead to chipping and damage of the gear. These chips can cause the steering to bind or stick during a turn. The "bind/stick" condition could result in a decrease of vehicle control and a vehicle crash without warning.

| | |
|---|--|
| <i>The problem is...</i> | The steering gear can bind/stick during a turn. |
| <i>What your dealer will do...</i> | Inspect the steering gear, and replace it if necessary. |
| <i>What you must do ...</i> | Contact your dealer immediately to schedule an appointment to have the defective gear inspected, and possibly replaced, at no cost to you. |

Kenworth has initiated a recall to inspect and replace the steering gear when necessary. Please contact your Kenworth dealer immediately to schedule an appointment for this inspection. To find your nearest Kenworth dealer, please visit Dealer Locator at www.Kenworth.com. This procedure should take no more than a few minutes to inspect and 2.7 hours to replace, and will be performed at no charge to you. If you had this repair performed before you received this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy of the problem associated with this recall.

If you require further information about this recall, reimbursement of a pre-notification remedy associated with this recall or experience any difficulty in making arrangements for this repair, please contact: Kenworth Truck Company, P.O. Box 1000, Kirkland, WA 98083-1000, Attn: Customer Service Department, phone 425-828-5000.

If you conclude that Kenworth Truck Company has not enabled you to remedy this defect in reasonable time and without charge, you may submit a complaint to: Administrator for Safety Assurance, National Highway Traffic Safety Administration, 400 Seventh Street, S.W., Washington, DC 20590, or call the toll free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

If you no longer own this vehicle, we would appreciate your advising us of the new owner if you know their name. The enclosed card may be used for this purpose.

We regret any inconvenience that this work may cause you and appreciate your cooperation in this matter.

Sincerely,

Mike Kalkoske
Quality Services Manager

January 9, 2008

VIN: _____


**SUBJECT: SAFETY RECALL # 1107K
TRW TAS-85 Steering Gear
EXPIRATION DATE: NONE**

Dear Peterbilt Customer:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Peterbilt Motors has decided that a defect which relates to motor vehicle safety exists in some vehicles manufactured between August 24, 2007 and November 21, 2007 with a TAS-85 steering gear. Your vehicle has been identified as having been manufactured within this time period and may contain a defect.

TRW Automotive informed Peterbilt Motors that certain steering gears were manufactured with a defective Sector Shaft. A defective Sector Shaft may shed metal material inside the steering gear which may cause the steering gear to bind or stick while the vehicle is turning. This situation may lead to difficult steering or vehicle crash. This situation may occur without warning and may involve personal injury or death.



| | |
|---|--|
| <i>The problem is...</i> | Defective steering gear Sector Shaft |
| <i>What your dealer will do...</i> | Inspect the steering gear lot and serial code and replace if necessary |
| <i>What you must do ...</i> | Contact your dealer immediately to schedule an inspection |

Peterbilt Motors Company has initiated a recall to inspect the steering gear serial number and lot code and, if necessary, replace the steering gear. Please contact your Peterbilt dealer immediately to schedule an appointment. This should take no more than a few minutes to inspect and 2.7 hours to replace. These services will be provided at no charge to you.

If you require further information, have already experienced this condition and have paid to have it repaired, or experience any difficulty in making arrangements for the repair, please contact: Peterbilt

Motors Company, 1700 Woodbrook Street, Denton, Texas 76205; Customer Service Department, phone 940-591-4196.


If you conclude that Peterbilt Motors Company has not enabled you to remedy this defect within a reasonable time and without charge, you may submit a complaint to: Administration for Safety Assurance, National Highway Traffic Safety Administration, 1200 New Jersey Avenue SE, Washington DC 20590, or call the toll free safety hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

If you no longer own this vehicle, we would appreciate your advising us of the new owner if you know their name. The enclosed card may be used for this purpose.

We regret any inconvenience that this work may cause you and appreciate your cooperation in this matter.

Sincerely,

A handwritten signature in black ink, appearing to read "Rick Wood". The signature is stylized and cursive.

Rick Wood
Quality Services Manager