

**LAND ROVER QUARTERLY SAFETY COMPLETION REPORT -- 49 CFR Part 573.7**  
**Quarter Ending September 30, 2007**

SAFETY RECALL NO.		QUARTERS REPORTED			OWNER NOTIFICATION		NOTES	VEHICLES INVOLVED	PROCEDURES COMPLETED <sup>1/</sup>		UNREACHABLE VEHICLES <sup>2/</sup>				
NHTSA	LAND ROVER	No.	FIRST	LAST	BEGAN	ENDED			INSPECTED	REPAIRED	UNDELIVERED	EXPORTED	STOLEN	SCRAPPED	OTHER
07V-041	P004	1	3Q-07	4Q-08	13-Aug-2007	13-Aug-2007	a/	33,305	0	7,156	1,137	0	0	0	0
07V-011	P001	3	1Q-07	2Q-08	16-Mar-07	16-Mar-07		6,134	0	4,929	112	0	0	0	0
06V-131	B037	5	3Q-06	4Q-07	30-Jun-06	30-Jun-06		45,900	0	41,636	650	0	0	0	0
06V-135	B039	5	3Q-06	4Q-07	30-Jun-06	30-Jun-06		10,791	0	9,862	241	0	0	0	0

**NOTES**

1/	"Procedures Completed" indicates the number of vehicles on which reports of action have been received from dealers and processed by Land Rover as of the end of the reporting period. Those in the "inspected" category were found to not require the recall service. Those in the "repaired" category did have the recall service performed.
2/	"Unreachable Vehicles" indicates the number of vehicle owners that could not be reached. "Undelivered" represents the number of first-class letters to owners of recalled vehicles, as shown on Company records, returned by the United States Postal Service for reasons such as addressee unknown, no such street number, or no such business office in the state. "Exported" represents the number of recalled vehicles reported to have moved out of the United States, its protectorates or territories. "Stolen" or "scrapped" represents the number of recalled vehicles reported to be either stolen or scrapped such that the safety recall service cannot be performed or is inappropriate. Those in the "other" category are vehicles either "modified" or where the owner "refused" the recall service.
a/	07V-041 / P004 Letters were mailed in March 2007 alerting owners of Land Rover recall P002 which was an interim repair until parts were expected to become available in May 2007. Interim repair P002 was included in the 1st and 2nd Quarter 2007 completion reports submitted to NHTSA. Letters were mailed in August 2007 alerting owners of Land Rover recall P004 which is the permanent repair. All owners have been instructed to have the permanent repair completed on their vehicles, regardless of whether or not the interim repair has been performed. Because no additional interim repairs will be performed by Land Rover, P002 will no longer be included on quarterly completion report submissions.