



HYUNDAI DE PUERTO RICO
C/O MMSC
Road 2 Km. 20.1 Candelaria Ward, Toa Baja, PR 00949
P.O. Box 192216, San Juan, PR 00919-2216
Tel. (787) 999-4310 Fax (787) 251-3024 / 8700
www.hyundaipr.com

January 17, 2008

VIA Fax No. 1-(202)-366-7882

Ms. Kathleen DeMeter
Director, Office of Defects Investigation
National Highway Traffic Safety Administration
400 Seventh Street, S.W.
Washington D.C. 20590

**Re: NHTSA Campaign No. 07V-197 – Air Bag Module Replacement
3rd Quarterly Report.**

Dear Ms. DeMeter:

Hyundai of Puerto Rico, C/O MMSC submits this letter for purposes of compliance with the quarterly reporting requirements of 49 C.F.R. Section 573.6. The following information is submitted for the calendar quarter ending December 31, 2007. This recall involves the following vehicles distributed by Hyundai of Puerto Rico: ***Model years 2005 through 20007 Hyundai Tucson vehicles produced beginning July 03, 2004 through November 1, 2006.***

The following information is identified by and in the order of the paragraph headings of Section 573.6(b):

1. The notification campaign number assigned by NHTSA: **No. 07V-197**
2. Date of notification began and the date completed: ***Due a shortage of parts from the manufacturer, notification to customers has to be delayed, beginning and completed on September 6, 2007. No second notification had been requested up to date.***
3. Number of vehicles involved in the campaign: **2,967**
4. The number of vehicles and equipment items, which have been inspected and repaired and the number of vehicles and equipment items inspected and determined there is no need to repair:

07V-197

a. Inspected	692
b. Repaired	692
c. Inspected and determined no need to repair	0

5. The number of vehicles determined to be unreachable for inspection due to export, theft, scrapping, failure to receive notification or other reasons (specify). The number of vehicles or items of equipment in each category shall be specified: As of December 31, 2007, the number of vehicles determined to be unreachable for inspection due to:

a. Export	0
b. Theft	0
c. Scrapping	0
d. Failure to receive notice (Undeliverable mail) *	199

*Returned notification letters are been sent to Sales Dealer to contact owners of affected units through the sales registration address information, home/work telephone and/or cellular number.

If you require any additional information, please do not hesitate to contact the undersigned at (787) 251-8715 Ext. 2248.

Sincerely,

Jorge A Viera Tirado
Service Engineer
Service Department, HDPR

C: J. Belk Arce, Legal Counselor
J. Rivera, Parts & Service Director