



Mr. George Person  
Chief, Recall Management Office  
National Highway Traffic Safety Adm.  
400 7th Street, S.W.  
Washington, D.C. 20590

26 March 2008

Dear Mr. Person:

The mailing of the Customer and Dealer Notifications for Recall 07V-241 began on 19 March and was completed on 21 March 2008. As required, copies of the final notifications are being faxed for your files. Original copies are being forwarded to your attention via certified mail.

Please feel free to contact me at 541-998-3720 x8382 should you have any questions.

Sincerely,

Dick Sabath  
Senior Manager, Warranty and Compliance Administration  
Country Coach Inc.

Enclosures (2) Customer Notification, 07V-241  
Dealer Notification, 07V-241



VIA: CERTIFIED MAIL, RETURN RECEIPT REQUESTED, AND  
FIRST CLASS MAIL

24 March 2008

**RE: Notification of Vehicle Safety Defect  
Federal Recall Campaign 07V-241**

Dear Country Coach Service Provider:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act, CFR 49, 573.5 and 573.6.

**DESCRIPTION OF NONCOMPLIANCE:**

Country Coach has decided that certain Inspire motor homes manufactured between March 2003 and May 2007 lamp assemblies do not meet requirements of Federal Motor Vehicle Safety Standard No. 108, "Lamps, Reflective Devices, and Associated Equipment". That the side marker lights in the combination headlight and tail light assemblies do not meet the minimum photometric values in FMVSS No. 108.

The inadequacy of the front and rear side marker lights could affect visibility of the motor home during hours of darkness and could potentially result in a motor vehicle crash.

**MODELS AFFECTED:**

**Model Year:** 2004 Inspire motor homes manufactured from March 2003 through March 2004

**VIN Range:** 4U7K5EK151103318 – 4U7K6EK1241103919

**Model Year:** 2005 Inspire motor homes manufactured from March 2004 through February 2005

**VIN Range:** 4U7K6ES1751103920 – 4U7K6ES1551104712

**Model Year:** 2006 Inspire motor homes manufactured from February 2005 through July 2006

**VIN Range:** 4U7K6ES1561104713 – 4U7K6ES1161061089

**Model Year:** 2007 Inspire motor homes manufactured from July 2006 through May 2007

**VIN Range:** 4U7K6DS1371060198 – 4U7K6DB1271060312

*See Attached Listing for Specific Coach Numbers*

To correct the condition noted above, Country Coach has decided that the repair for these defects will be installation of four side marker lights. Marker lights will be placed on each motor home as close as reasonable to the front and rear corners and wired into the park light system. All removed parts must be **destroyed**. The amount of labor required to perform this remedy is not expected to exceed **2.0** hours. This work will be performed at no cost to the consumer.

If the condition is not adequately repaired within a reasonable time, the owner may be entitled to an identical or reasonably equivalent motor home at no charge or to a refund of the purchase price less a reasonable allowance for depreciation.

To avoid having to provide these burdensome solutions, every effort must be made to promptly schedule an appointment with owners and to repair their motor homes as soon as possible. You should be aware that owners are instructed to contact the customer service department if their dealer does not remedy the condition within three (3) days of the mutually agreed upon service date. (Please see the enclosed Letter to Country Coach Owners) Owners are also advised to contact the National Highway Traffic Safety Administration if the condition is not remedied without charge and within a reasonable time.

Sincerely,

A handwritten signature in black ink, appearing to read "Dick Sabath", with a long horizontal flourish extending to the right.

Dick Sabath,  
Senior Manager, Compliance Administration  
Country Coach LLC

Enclosure: Customer Notification



VIA: CERTIFIED MAIL, RETURN RECEIPT REQUESTED, AND  
FIRST CLASS MAIL

24 March 2008

**RE: Owner Notification of Vehicle Safety Defect  
Federal Recall Campaign 07V-241**

Dear Country Coach Owner:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act, CFR 49, 573.5 and 573.6.

**DESCRIPTION OF NONCOMPLIANCE:**

Country Coach has decided that certain Inspire motor homes manufactured between March 2003 and May 2007 lamp assemblies do not meet requirements of Federal Motor Vehicle Safety Standard No. 108, "Lamps, Reflective Devices, and Associated Equipment". That the side marker lights in the combination headlight and tail light assemblies do not meet the minimum photometric values in FMVSS No. 108.

The inadequacy of the front and rear side marker lights could affect visibility of the motor home during hours of darkness and could potentially result in a motor vehicle crash.

**MODELS AFFECTED:**

**Model Year:** 2004 Inspire motor homes manufactured from March 2003 through March 2004

**VIN Range:** 4U7K5EK151103318 – 4U7K6EK1241103919

**Model Year:** 2005 Inspire motor homes manufactured from March 2004 through February 2005

**VIN Range:** 4U7K6ES1751103920 – 4U7K6ES1551104712

**Model Year:** 2006 Inspire motor homes manufactured from February 2005 through July 2006

**VIN Range:** 4U7K6ES1561104713 – 4U7K6ES1161061089

**Model Year:** 2007 Inspire motor homes manufactured from July 2006 through May 2007

**VIN Range:** 4U7K6DS1371060198 – 4U7K6DB1271060312

*See Attached Listing for Specific Coach Numbers*

To correct the condition noted above, Country Coach has decided that the repair for these defects will be installation of four side marker lights. Side marker lights will be placed on the side of each motor home as close as reasonable to the front and rear corners and wired into the park light system. All removed parts must be **destroyed**. The amount of labor required to perform this remedy is not expected to exceed **2.0** hours. This work will be performed at no cost to the consumer.

Please present this letter and the enclosed warranty claim to the dealer/service facility when you take your motor home to be serviced. The dealer/service facility that does the repairs will need the warranty claim for billing.

Should you need assistance in locating your nearest Country Coach dealer, please contact Country Coach's customer service department at 1-800-452-8015. The service department will refer you to a service facility near you. If the dealer/service facility fails to remedy the noncompliance on the agreed upon service date or within three (3) days of the scheduled service date, please contact Country Coach customer service by calling 1-800-452-8015 and ask for the Technical Service Representative handling this recall.

You may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy of a problem associated with this recall. For more information regarding this contact Country Coach Compliance Administration at 1-800-452-8015, extension 8382.

If you no longer own this motor home, please complete and return the Vehicle Owner Reply Card in the self-addressed postage paid envelope included in this package.

If after contacting both your dealer/service facility and Country Coach you are not able to have the noncompliance remedied within a reasonable time and/or at no cost to you, you may wish to contact the National Highway Traffic Safety Administration:

Administrator  
National Highway Traffic Safety Administration  
1200 New Jersey Avenue SE  
Washington D.C. 20590


Or call the Vehicle Safety Hotline's toll free number at 1-888-327-4236 (TTY: 1-800-424-9153)

Or go to <http://www.safercar.gov>

Federal regulations requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days after receipt of the original notification.

We are sorry for this inconvenience; however, we have taken this action in the interest of your safety and continued satisfaction with your motor home.

Sincerely,



Dick Sabath  
Senior Manager, Compliance Administration  
Country Coach, LLC