

Federal Recall Information

607-G

Supplier

Bendix Commercial Vehicle Systems LLC

Description

This recall is related to the internal check valve of the Bendix SR-7 spring brake modulating valve.

Release Date

TBD

Introduction

Bendix has notified Peterbilt that there is a potential safety defect with respect to the internal rubber check valve inside the Bendix SR-7 spring brake modulating valves.

Situation

Bendix's component supplier made unauthorized changes to its manufacturing process. The effect of this defect is intermittent and presents a potential delay or failure in applying the parking brakes; potentially resulting in a vehicle roll away.

Affected vehicles were built between September 19, 2006 and May 31, 2007.

Resolution

This recall provides instructions to replace the internal rubber check valve of the SR-7 spring brake modulating valve.

It is a violation of Federal law for a dealer to sell or lease new vehicles covered by this recall until the defect or noncompliance has been corrected.

Warranty

The DWC system will indicate chassis involved in this recall with the designator of "607-G" in the campaign field. Please use Quick claim TBD for this recall.

Parts

Peterbilt will cover parts purchased through PACCAR Parts (dealer net+ 30% parts mark up) according to the schedule below.

PARTS			
Qty	Part Number	Description	DealerNet(USD)
1	K022699BXW	INTERNAL CHECK VALVE CARTRIDGEKIT	1.48 ea

Labor

Peterbilt will cover labor according to the schedule below.

Labor		
013-XXX	0.8 hr	REPLACE INTERNAL CHECK VALVE

Parts return are not required.

Procedure

Please refer to the following documents when you repair the SR-7 spring brake modulating valve.



Plumbing schematic with optional hand valve



Plumbing schematic without hand valve plumbed to brakes



Bendix Installation procedures

Shipping

Freight

Contact

Attachments



607-G Customer Letter 607Gdealerchassislist.pdf

© Copyright 2007 PACCAR Inc, All Rights Reserved.