

May 2008

To: **All Affected US Roadtrek Owners**

From: **Ben Spengen, Service, Warranty & Parts Manager**

RE: **Second Notice of Recall 2007-01 (NHTSA 07V-036) Brass Connector Fitting (210C Models)**

This is a follow up to a notice that was sent to you in February 2007. Our records indicate that you have not yet had the repair work done on your vehicle.

Roadtrek Motorhomes Inc. (formerly Home & Park Motorhomes) has decided that a defect which relates to motor vehicle safety exists in the brass connector fitting at the refrigerator installed in Roadtrek 210 class 'B' Motorhomes manufactured on Chevrolet 3500 chassis between July 2006 and January 2007.

The recall pertains to a brass connector fitting used to connect the copper piping from the motorhome propane storage container to the brass fitting assembly behind the refrigerator. It is a possibility; the connection will leak with vehicle usage, vibration etc., resulting in a possible fire hazard.

As a warning to the presence of a propane gas leak, you can notice the distinct rotten egg odor.

Corrective action requires the brass connector fitting to be inspected and replaced if required. This brass connector fitting can be easily viewed from behind the refrigerator exterior access door. See attached photographic images for determining if your vehicle is equipped with a defective brass connector fitting.

The service and required parts if required, will be provided free of charge. The work will take about 2 hours to complete. However, additional time may be required depending on how dealer appointments are scheduled and processed. To obtain this free service, contact your Roadtrek dealer service department at your earliest convenience for inspection and correction. If you no longer own this vehicle, please inform the dealer or Roadtrek of this when you call. For more information contact our Service and Warranty department toll free at 1-888-ROADTREK (762-3873).

If this notification is inadequate or the corrections are not made in accordance with this notification within 60 days, you may advise the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE., Washington, DC 20590; or call the toll free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

You are requested to carry out the inspection. If you have the correct fitting, please complete and return the recall form. If your vehicle is equipped with the defective brass fitting, **do not use the propane system in your Roadtrek**. Contact your Roadtrek dealer for immediate service to replace the fitting.

We regret any inconvenience these actions may cause.




Figure 1: Photographic image illustrating defective fitting installation.




Figure 2: Photographic image illustrating correct fitting installation.