

1200 New Jersey Avenue SE Washington, DC 20590

July 31, 2008

MR. WILLIAM R. WILLEN MANAGING COUNSEL PRODUCT REGULATORY OFFICE AMERICAN HONDA MOTOR CO., INC. 1919 TORRANCE BOULEVARD TORRANCE CA 905012746 NVS-215dgl 08V-349

Subject: IMPROPER WELDED SUSPENSION

Dear MR. WILLEN:

This letter serves to acknowledge American Honda Motor Company, Inc.'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety defect in the products described below for which a safety recall campaign shall be conducted pursuant to 49 U.S.C. § 30119.

Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years: HONDA/ELEMENT/2008 Mfg's Report Date: July 25, 2008

NHTSA Campaign Number: 08V-349

Components: SUSPENSION: REAR

Potential Number of Units Affected: 241

Summary:

HONDA IS RECALLING 241 MY 2008 ELEMENT VEHICLES. THE FRONT BUSHING BRACKET OF THE LEFT TRAILING ARM OF THE REAR SUSPENSION MAY HAVE BEEN IMPROPERLY WELDED AND COULD SEPARATE FROM THE TRAILING ARM.

Consequence:

A SEPARATED BUSHING BRACKET COULD CAUSE THE SUSPENSION TO RELEASE THE LOWER PORTION OF THE WHEEL HUB, CAUSING A LOSS OF CONTROL AND DAMAGE TO THE BRAKE SYSTEM WHICH COULD LEAD TO A CRASH.

Remedy:

OWNERS WILL BE CONTACTED BY PHONE AND ADVISED TO STOP DRIVING THEIR VEHICLES UNTIL THEY HAVE TAKEN THEIR VEHICLE TO A DEALER FOR INSPECTION. DEALERS WILL INSPECT THE LEFT REAR TRAILING ARM AND, IF NECESSARY, REPLACE IT FREE OF CHARGE. THE RECALL IS EXPECTED TO BEGIN DURING JULY 2008. OWNERS MAY CONTACT HONDA AT 1-800-999-1009.

Notes:

HONDA RECALL NO. 08-053. CUSTOMERS MAY ALSO CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION'S VEHICLE SAFETY HOTLINE AT 1-888-327-4236 (TTY 1-800-424-9153), OR GO TO <u>HTTP://WWW.SAFERCAR.GOV</u>.

Please provide the following additional information and be reminded of the following requirements:

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on or before 30 days after the close of the calendar quarter.

Your contacts for this recall will be Pat Wallace or Delia Lopez, who may be reached by phone at 202-366-5232 or 202-366-9525 or by email at <u>Patricia.wallace@dot.gov</u>, <u>Delia.lopez@dot.gov</u>, or through the office email at <u>RMD.ODI@dot.gov</u>. We look forward to working with you for successful completion of this recall campaign.

Sincerely,

George H. Person Chief, Recall Management Division Office of Defects Investigation, Enforcement