



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

October 24, 2008

MR. JAN URBAHN
GENERAL MANAGER, SAFETY ENGINEERING
AND INTELLIGENT TRANSPORTATION SYSTEMS
BMW OF NORTH AMERICA, LLC
PO BOX 1227
WESTWOOD, NJ 07675-1227

NVS-215dgl
08V-564

Subject: PARALEVER LINK FASTENER

Dear MR. URBAHN:

This letter serves to acknowledge BMW North America, LLC's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety defect in the products described below for which a safety recall campaign shall be conducted pursuant to 49 U.S.C. § 30119.

Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:
BMW/HP2 ENDURO/2005-2006

NHTSA Campaign Number: 08V-564

Mfg's Report Date: October 2, 2008

Components: SUSPENSION

Potential Number of Units Affected: 365

Summary:

BMW IS RECALLING 365 MY 2005-2006 HP2 ENDURO MOTORCYCLES. THE FRONT THREADED FASTENER OF THE PARALEVER LINK MAY NOT HAVE BEEN TIGHTENED TO CORRECT SPECIFICATIONS. IF THE FASTENER WAS NOT TIGHTENED ACCORDING TO SPECIFICATIONS, IT COULD LOOSEN. OVER TIME, IT IS POSSIBLE FOR THE FASTENER TO SEPARATE FROM ITS HOUSING. IF THIS WERE TO OCCUR, THEN THE FINAL DRIVE OF THE MOTORCYCLE WOULD NOT BE PROPERLY SUPPORTED.

Consequence:

IF THAT HAPPENED, THEN MOTORCYCLE HANDLING WOULD BE COMPROMISED INCREASING THE RISK OF A CRASH.

Remedy:

DEALERS WILL REMOVE THE FRONT THREADED FASTENER OF THE PARALEVER LINK AND REPLACE IT WITH AN IMPROVED FASTENER. THE RECALL IS EXPECTED TO BEGIN DURING OCTOBER 2008. OWNERS MAY CONTACT BMW AT 1-800-831-1117.

Notes:

CUSTOMERS MAY ALSO CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION'S VEHICLE SAFETY HOTLINE AT 1-888-327-4236 (TTY 1-800-424-9153), OR GO TO [HTTP://WWW.SAFERCAR.GOV](http://www.safercar.gov).

We have reviewed your proposed owner notification letter and it meets the requirements of Part 577.

Please provide the following additional information and be reminded of the following requirements:

BMW must file a sample of the envelope which you intend to use to mail the recall notice to owners. The words "SAFETY", "RECALL", "NOTICE" in any order must be printed on the envelope in larger font than the customers name and address.

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on or before 30 days after the close of the calendar quarter.

Your contacts for this recall will be Pat Wallace or Delia Lopez, who may be reached by phone at 202-366-5232 or 202-366-9525 or by email at Patricia.wallace@dot.gov, Delia.lopez@dot.gov, or through the office email at RMD.ODI@dot.gov. We look forward to working with you for successful completion of this recall campaign.

Sincerely,

A handwritten signature in cursive script that reads "Patricia Wallace for".

George H. Person
Chief, Recall Management Division
Office of Defects Investigation
Enforcement