



December 3, 2008

MR. JAMES P. VONDALE DIRECTOR, AUTOMOTIVE SAFETY OFFICE FORD MOTOR COMPANY 330 TOWN CENTER DRIVE, SUITE 400 DEARBORN MI 48126-2738 NVS-215paw 08V-635

SUBJECT: FRONT DRIVESHAFT JOINT REPLACEMENT

DEAR MR. VONDALE:

This letter serves to acknowledge Ford Motor Company's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety defect in the products described below for which a safety recall campaign shall be conducted pursuant to 49 U.S.C. § 30119.

Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

LAND ROVER/RANGE ROVER/2003-2005

NHTSA Campaign Number: 08V-635

Mfg's Report Date: December 2, 2008

Components: POWER TRAIN: DRIVELINE: DRIVESHAFT

Potential Number of Units Affected: 19,168

Summary:

LAND ROVER IS RECALLING 19,168 MY 2003-2005 RANGE ROVER VEHICLES. THE FRONT DIFFERENTIAL COUPLING SLEEVE AND THE PROPELLER SHAFT MAY BE MISALIGNED, RESULTING IN SPLINE WEAR OVER A PERIOD OF TIME. AS THE WEAR BETWEEN THE PROPELLER SHAFT AND THE DIFFERENTIAL SPLINE COUPLING PROGRESSES, NOISE AND VIBRATION ARE EXPECTED.

Consequence:

CONTINUED VEHICLE OPERATION CAN EVENTUALLY RESULT IN THE SPLINES SHEARING AND A LOSS OF DRIVE, INCREASING THE RISK OF A CRASH.

Remedy:

DEALERS WILL INSTALL A REVISED DESIGN OF THE PROPELLER SHAFT, THE FLANGE KIT AND HEAT SHIELD KIT. THE RECALL IS EXPECTED TO BEGIN ON OR ABOUT JANUARY 6, 2009. OWNERS MAY CONTACT LAND ROVER AT 1-800-637-6837.

Notes:

LAND ROVER RECALL NO. P041. CUSTOMERS MAY ALSO CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION'S VEHICLE SAFETY HOTLINE AT 1-888-327-4236 (TTY 1-800-424-9153), OR GO TO HTTP://WWW.SAFERCAR.GOV.

This recall was the subject of an Engineering Analysis, EA07-012, conducted by the Office of Defects Investigation.

The information in your defect report appears to satisfy the requirements of 49 CFR 573.6 except for the following items:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Land Rover must file a sample of the envelope which you intend to use to mail the recall notice to owners. The words "SAFETY", "RECALL", "NOTICE" in any order must be printed on the envelope in larger font than the customers name and address.

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on or before 30 days after the close of the calendar quarter.

Your contacts for this recall will be Pat Wallace or Delia Lopez, who may be reached by phone at 202-366-5232 or 202-366-9525 or by email at Patricia.wallace@dot.gov, Delia.lopez@dot.gov, or through the office email at RMD.ODI@dot.gov. We look forward to working with you for successful completion of this recall campaign.

Sincerely,

George H. Person

Chief, Recall Management Division Office of Defects Investigation

Enforcement