



Concrete
Mixing Equipment

Zimmerman Industries, Inc.

196 Wabash Road
Ephrata, PA 17522-9622


Toll Free: 888/577-6499
Phone: 717/733-6166
Fax: 717/733-1169
E-mail: info@zimmermanindustries.com
Web Site: www.zimmermanindustries.com

08V-081
(3 Pages)

On July 17, 2007, Zimmerman Industries Inc. received a letter from Watson & Chalin Mfg. Inc. that was dated July 15, 2007, informing us that a defect, which relates to motor vehicle safety, exists and is furnishing notification to National Highway Traffic Safety Administration in accordance with 49 CFR Part 573 Defect and Noncompliance Responsibility and Reports. I understand that ignorance of the law is no excuse and apologize for the tardiness of this report, having learned very much in the past week.

Date this report was prepared: February 11, 2008

1. Zimmerman Industries Inc.
196 Wabash Rd.
Ephrata, PA 17522
Phone: 717-733-6166
Fax: 717-733-1169
Contact: Jerry L. Stoner, President
E-mail: jerry@zimmermanindustries.com



Jerry L. Stoner

RECEIVED
2008 FEB 25- 8:50 AM
RECALL MANAGEMENT
DIVISION

I. Identify the Vehicle Models Involved in the Recall

2. 2006 Sterling model LT 8500, VIN #2FZHAWDJ66AV52298 with a ZM4-407-1616-06 Zim-Mixer® body and a Watson & Chalin Mfg. Inc. SL-1190 auxiliary axle installed.

II. Identifying the Recall Population

3. We are recalling one unit as this is the only unit that has the Watson & Chalin Mfg. Inc. SL-1190 auxiliary axle installed.
4. This unit clarifies 100% of the units that are affected as this is the only unit which has the Watson & Chalin Mfg. Inc. SL-1190 auxiliary axle installed.

III. Describe the Defect or Noncompliance

5. The defect is in the lower aluminum trailing arms that is described in the Watson & Chalin Mfg. Inc. recall notice dated July 15, 2007. The defect is in a component purchased from Watson & Chalin Mfg. Inc., 725 E. University Dr., McKinney, TX 75069. Phone: 972-547-6020. Contact: Thomas N. Chalin.

IV. Provide the Chronology in Determining the Defect

6. We were sent a letter of defect by Watson & Chalin Mfg. Inc. dated July 15, 2007, saying that the lower aluminum arms may be defective. The letter stated that they would be contacting us by phone, which Ron Stansfield did approximately two weeks later. Mr. Kidhardt gave the owner information to Mr. Stansfield who stated that he would follow up with all recourse.

V. Identify the Remedy

8. We have given all pertinent customer information to Watson & Chalin Mfg. Inc., who in turn will be supplying new arms, hardware and three hours of labor to replace the defect as stated in their letter dated July 15, 2007.
9. Sec 8 above.

VI. Identify the Recall Schedule

10. See Watson & Chalin Mfg. Inc. report dated August 17, 2007.