



Polaris Industries Inc.
Product Development Center
7290 Viking Blvd E
Wyoming, MN 55092
T: 651-408-7579
F: 651-408-7605

March 14, 2008

08V-131
(11 pages)

National Highway Traffic Safety Administration
Patricia Wallace, Office of Defects Investigation
1200 New Jersey Avenue, SE
Washington, D.C. 20590
T: (202) 366-5232
F: (202) 366-7882

Dear Ms. Wallace:

573.6 Defect Information Report

573.6.c.1.

Vehicle manufacturer's full name:

Polaris Industries Inc., Victory Motorcycle Division

Address:

2100 Highway 55
Medina, MN 55340-9800

573.6.c.2.

Vehicles potentially containing defect:

MY 2008 Victory Vision motorcycles.

Vehicle Identification Numbers:

A list of affected VINs is attached separately as Attachment c.2.

Inclusive dates of manufacture:

May 14, 2007 through March 3, 2008.

Basis for recall population:

All MY 2008 Victory Vision motorcycle models manufactured up to March 3, 2008.
Machines built after March 3, 2008 have not been shipped and will be repaired prior to shipping.

573.6.c.3.

Total number of vehicles potentially containing defect:

A total of 1585 vehicles may contain this defect.

RECEIVED

2008 MAR 20 A 10:35

DEFECTS INVESTIGATION
RECALL MGMT DIV.

573.6.c.4.

Percentage of vehicles estimated to actually contain defect:

Victory estimates that approximately 20 percent of the manufactured units may have this defect.

573.6.c.5.

Brief Summary:

Victory has determined that a defect may exist in the ignition switch assembly which may cause an intermittent or nonexistent connection when the switch is placed in the run position. A poor connection in the ignition switch could cause a lack of battery voltage to reach the Engine Control Module (ECM) and other electrically controlled components of the motorcycle.

08V-131
(11 pages)

Detailed description:

Victory has determined that some ignition switch assemblies were delivered to Victory by its supplier in a condition where the bottom connector plate was not secured properly in the switch body. The root cause of the issue is due to inadequate process control during the ignition switch manufacturing process. The improper assembly of the ignition switch can cause a loss of connection between the connector plate and the internal switch terminals.

If a poor ignition switch connection were to exist, the machine might exhibit an intermittent misfire or the engine may unexpectedly shut off. The lighting system of the vehicle would also display intermittent or no operation if this condition were to exist.

573.6.c.6.

Chronology:

Victory is aware of six field reports of failed ignition switches. Four of the instances displayed the symptom where the machine could not be started. One machine developed a driveability problem and one machine lost all electrical function while the machine was being operated. No accidents or injuries have been reported.

The first failure occurred on 11-20-07 and another failure was reported on 1-3-2008.

Victory was not aware of the other four failures as the dealers did not file warranty claims for the problems. Victory only became aware of them when the dealers were called in the week of March 3, 2008 to gather more information about the failures that were reported. Upon talking to the technicians at the dealerships, the technicians indicated that they had seen other failures that they had corrected for which they had not filed warranty claims.

Victory also observed three instances of a poor electrical connection in the last week of February, 2008 during the final inspection process at the Sprit Lake, IA assembly facility.

Once Victory determined that an electrical problem with the electrical system might be present, Victory stopped shipment of vehicles and began investigating the issue. This investigation revealed that some ignition switches were not assembled correctly.

573.6. c.8.

Remedy program:

For machines that have been shipped to its dealer network, Victory will conduct a safety recall by which we will require our dealer network to repair the ignition switch assembly. Machines that have not been shipped out of Victory's control will be repaired prior to being shipped.

Estimated date on which notifications to Owners will begin:

March 31, 2008.

Estimated date on which notification will be completed:

April 7, 2008.

08V-131
(11 pages)

573.6.c.10.

Owner letter:


See attached draft of Owner Notification letter.

573.6.c.11.

Manufacturer's campaign number:

V-08-01

Signed:



Date:

3-14-2008

Don L. Good

Product Compliance Specialist

Polaris Industries Inc.

Attachments

Proposed Safety Recall Bulletin

Page(s) 4, 5

Proposed Consumer Notification

Page 6

Bulletin Kit Instructions

Page 7

Affected VINs

Page(s) 8, 9, 10, 11



THE NEW AMERICAN MOTORCYCLE™
Date: 03/xx/2008

TECHNICAL SERVICE BULLETIN

Victory Motorcycle

Bulletin Number: **V-08-01**
Model Years: **2008**

☐ Safety Bulletin ☒ **Safety Recall** ☐ Service Bulletin ☐ Service Alert Fax ☐ Production Update Kit

Distribution: ☐ Owner / Principal

This Service

DRAFT COPY

or ☐ Parts Manager ☐ Technicians

dealers.com



SUBJECT: Ignition Switch Improperly Assembled

08V-131
(11 pages)

PURPOSE: The electrical contact plate on the ignition switch base may not be properly secured to the ignition switch body, which can cause a loss of electrical power to the vehicle. A loss of electrical power could cause the vehicle to stall, increasing the risk of a loss of control and a vehicle crash.

AFFECTED MODEL(S):

Model	Model Number(s)	Vehicle Identification Numbers (VIN)
2008 Victory Vision Street™	V08S136; V08SB36CAP, CCP, CD, CDP V08SB36DA, DAP, DC, DCP, DD, DDP V08SB36LAP, LC, LCP, LD, LDP	Enter the VIN number in "Unit Inquiry" on the dealer website to determine if this bulletin applies before performing this repair.
2008 Victory Vision Tour™	V08S236; V08SD36CA, CAP, CAT, CC, CCP, CCT, CD, CDP, CDT V08SD36DA, DAP, DAT, DC, DCP, DCT, DD, DDP, DDT V08SD36LA, LAP, LAT, LC, LCP, LCT, LDP, LDT	Enter the VIN number in "Unit Inquiry" on the dealer website to determine if this bulletin applies before performing this repair.

WHAT YOUR DEALERSHIP SHOULD DO:

1. Enter the Vehicle Identification Number in unit inquiry to see if this bulletin applies.
2. If the vehicle is affected, follow instructions on page 4 to install the switch base retainer ring and shim from Service Kit P/N xxxxxxxx.
3. File a warranty claim immediately after completion of this bulletin. Follow warranty claim filing procedures on page 2.

CUSTOMER NOTIFICATION:

A customer Notification letter 08V-xx (08-xx in Canada) will be sent to registered owners of motorcycles affected by this bulletin. An example of the letter is shown on page 3.

In addition to the notification letter sent by Victory, dealers are required to notify owners of motorcycles sold by their dealership, and to make arrangements to perform this bulletin repair immediately.

PARTS INFORMATION:

V-08-01 Page 2 of 4

PART NUMBER / DESCRIPTION	TBD
QUANTITY	1 kit required per affected unit
DIRECT SHIP FROM VICTORY?	NO
TO BE ORDERED BY DEALERS?	YES
AVAILABLE TO ORDER	YES

WARRANTY CLAIM INFORMATION:

NEW WORDING: A single group claim may be submitted listing the complete 17-digit VIN for machines WITH THE SAME MODEL NUMBER. File claim type **SB (Service Bulletin)**. DO NOT ENTER MORE THAN ONE MODEL NUMBER ON A WARRANTY CLAIM. All warranty claims must be submitted within 10 days of the repair. Never submit a warranty claim before completing the work. It is in violation of your dealer agreement to submit a warranty claim prior to the work being completed. Removed components are to be retained according to the Polaris Warranty Policy for possible return to the Warranty Department

Service Bulletin Number	V-08-01
Claim Type	SB
Labor Allowance	:12 Minutes.
Claim Part Numbers	Automatically entered by warranty system

SERVICE BULLETIN COMPLETION DECAL:

- 1) Fill out a Service Bulletin Completion Decal, PN 7170107.
- 2) Clean the surface of the inside of the battery side cover.
- 3) Remove the decal from the sheet and apply as shown.
- 4) Peel adhesive backing off of the *clear* protective outer film of decal.
- 5) Press the clear film firmly over the decal.

If you require more decals, order them through normal parts ordering channels.



Fill out Decal with all required information.



Remove rear console cover and apply to underside.

Sincerely,

Laurie Rengel
Manager, Service Dealer Development and Warranty



Victory Motorcycle Division
of Polaris Industries Inc.
2100 Highway 55
Medina, MN 55340

March xx, 2008

SAFETY RECALL NOTICE

Recall Campaign: 08V-xxx (08-xxx in Canada)
Subject: Improperly Assembled Ignition Switch
Reference: Safety Recall Bulletin V-08-01

PLEASE READ IMMEDIATELY

CUSTOMER INFORMATION PRINTED HERE

Customer's VIN #
Customer's Name
Customer's Address

08V-131
(11 pages)

Dear Victory Owner:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. The Victory Motorcycle Division of Polaris Industries Inc. has decided that a defect which relates to motor vehicle safety exists in some 2008 Victory Vision™ motorcycles. Our records indicate that you have purchased a potentially affected vehicle.

The reason for this recall:

Victory has decided that a defect may exist in the ignition switch assembly on affected vehicles. The electrical contact plate on the ignition switch base may not be properly secured to the ignition switch body, which can cause an unexpected loss of electrical power to the vehicle. A loss of electrical power could cause the vehicle to stall, increasing the risk of a loss of control and a vehicle crash.

What Victory and your dealer will do:

Victory has issued *Safety Recall Bulletin V-08-01* to all Victory dealers, with instructions required to fully secure the ignition switch base to the switch body on all affected vehicles. Repairs will be made by any authorized Victory motorcycle dealer at no cost to you. The actual repair will take approximately 15 minutes to perform; however, it may take longer due to service scheduling requirements.

What you should do:

Please call your authorized Victory motorcycle dealer to schedule an appointment to have the bulletin repair performed. Do not attempt repairs yourself. Repairs must be done only by an authorized Victory motorcycle dealer.

DO NOT OPERATE YOUR MOTORCYCLE UNTIL ALL REPAIRS HAVE BEEN COMPLETED!

If you have questions or if you need more information:

While your Victory dealer is in the best position to answer your questions, if you have any questions that your dealer cannot address, if you are having difficulty obtaining the recall repair outlined in this letter, or if you need assistance finding a Victory Dealer, please contact our Victory Consumer Service Department by calling 1-888-704-5290 or visit the Polaris/Victory Motorcycle web site at www.polarisindustries.com.

This notice was mailed to you according to our most current registration information. If you no longer own your Victory motorcycle, please contact your local Victory dealer to have the ownership information changed. The Consumer Service Department cannot change ownership information without identification. Federal law requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within 10 days.

If you believe that the Victory Motorcycle Division of Polaris Industries Inc. has failed to remedy this defect without charge or is unable to do so within a reasonable time, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue SE., Washington, D.C. 20590; or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or on the web go to <http://www.safercar.gov>.

Please accept our apologies for any inconvenience this may cause you. Your safety and continued satisfaction with your Victory motorcycle is our primary concern. Thank you for your prompt attention to this matter.

Sincerely,

Laurie Rengel
Manager, Service Dealer Development & Warranty




IGNITION SWITCH BASE RETAINER KIT INSTRUCTIONS

KIT CONTENTS:

<u>QTY</u>	<u>Part Number</u>	<u>Description</u>
(1)	N/A	Ring, Retainer
(1)	N/A	Shim, Retainer

Overview: The retainer ring and shim can be installed with the console and all body work in place. Some part were removed for clarity in the photos below. Work from a seated position on the motorcycle or straddle the seat so you can use your left and right hands under the console. The retainer must be oriented properly with the large single opening in the ring facing UP and positioned over the ignition switch wire harness (at rear side of switch). With retainer in position, the shim is guided from right to left through the two slots on the bottom side of the retainer, then pulled firmly from the left side until seated. The shim is left in place under the retainer after installation.

1. Be surew the area around the switch base is clear of any wiring. Working from the RIGHT side of the console, slide the retainer into position under the switch base with the large single slot (A) facing upward and rearward. Align the slot with the switch wire harness (B). (Fig. 1)
2. Reach in from the LEFT and RIGHT sides and rotate the insert slightly as needed until you feel the upper slot straddle the wire harness. The two slots (C) on the bottom side should now be centered on left and right sides of switch base. (Fig.1)
3. Lift the retainer ring slightly and hold it in position with your left hand from the left side.
4. With the shim positioned as shown in Fig. 3, (stop tab on right end is pointed upward) slide the thin end of the taper into the right side slot and push the tool through until the end comes out through the left side slot.
5. Reach in from the left side and grasp the thin tapered end of the tool firmly.
6. Pull the tool toward the left side until the end tab stops against the right side of the switch.
7. Trim the left side of the shim to remove any visible portions.



VIN	VIN	VIN	VIN	VIN	VIN
5VPS136D083008774	5VPSB36D983001173	5VPSD36D183004210	5VPSD36D483003827	5VPSD36D783001408	5VPSD36D983004424
5VPS136D183008766	5VPSB36D983001237	5VPSD36D183004224	5VPSD36D483003830	5VPSD36D783001456	5VPSD36D983004455
5VPS136D183008802	5VPSB36D983002386	5VPSD36D183004238	5VPSD36D483003925	5VPSD36D783001523	5VPSD36D983004472
5VPS136D283008758	5VPSB36D983002405	5VPSD36D183004255	5VPSD36D483003973	5VPSD36D783001568	5VPSD36D983004486
5VPS136D483000144	5VPSB36D983003344	5VPSD36D183004286	5VPSD36D483004069	5VPSD36D783001571	5VPSD36D983004522
5VPS136D483008910	5VPSB36D983003683	5VPSD36D183004305	5VPSD36D483004072	5VPSD36D783001649	5VPSD36D983004536
5VPS136D483008941	5VPSB36D983004610	5VPSD36D183004319	5VPSD36D483004184	5VPSD36D783001652	5VPSD36D983004584
5VPS136D583000184	5VPSB36D983004624	5VPSD36D183004353	5VPSD36D483004198	5VPSD36D783001733	5VPSD36D983004682
5VPS136D783008495	5VPSB36D983004638	5VPSD36D183004367	5VPSD36D483004220	5VPSD36D783001778	5VPSD36D983004746
5VPS136D783008934	5VPSB36D983005577	5VPSD36D183004370	5VPSD36D483004234	5VPSD36D783001781	5VPSD36D983004780
5VPS136D883008750	5VPSB36D983005580	5VPSD36D183004384	5VPSD36D483004248	5VPSD36D783001800	5VPSD36D983004794
5VPS136D983000141	5VPSB36D983005837	5VPSD36D183004398	5VPSD36D483004251	5VPSD36D783001943	5VPSD36D983004830
5VPS136D983008515	5VPSB36D983005918	5VPSD36D183004420	5VPSD36D483004282	5VPSD36D783001957	5VPSD36D983004844
5VPS136D983008806	5VPSB36D983005921	5VPSD36D183004465	5VPSD36D483004296	5VPSD36D783002039	5VPSD36D983004858
5VPS136DX83008782	5VPSB36D983006602	5VPSD36D183004482	5VPSD36D483004301	5VPSD36D783002088	5VPSD36D983004875
5VPS236D083008786	5VPSB36D983006695	5VPSD36D183004496	5VPSD36D483004315	5VPSD36D783002249	5VPSD36D983004911
5VPS236D183008439	5VPSB36D983006714	5VPSD36D183004532	5VPSD36D483004329	5VPSD36D783002297	5VPSD36D983004925
5VPS236D183008778	5VPSB36D983006728	5VPSD36D183004546	5VPSD36D483004363	5VPSD36D783002414	5VPSD36D983004939
5VPS236D283008465	5VPSB36D983006731	5VPSD36D183004756	5VPSD36D483004380	5VPSD36D783002459	5VPSD36D983004987
5VPS236D283008790	5VPSB36D983006776	5VPSD36D183004790	5VPSD36D483004394	5VPSD36D783002462	5VPSD36D983005007
5VPS236D383008445	5VPSB36DX830001193	5VPSD36D183004806	5VPSD36D483004461	5VPSD36D783002607	5VPSD36D983005136
5VPS236D583008475	5VPSB36DX83000226	5VPSD36D183004840	5VPSD36D483004492	5VPSD36D783002610	5VPSD36D983005329
5VPS236D683008470	5VPSB36DX83000601	5VPSD36D183004854	5VPSD36D483004508	5VPSD36D783002655	5VPSD36D983005332
5VPS236D783008770	5VPSB36DX83000632	5VPSD36D183004921	5VPSD36D483004542	5VPSD36D783002784	5VPSD36D983005377
5VPS236D783008798	5VPSB36DX83000890	5VPSD36D183004935	5VPSD36D483004590	5VPSD36D783002865	5VPSD36D983005380
5VPS236D883008762	5VPSB36DX83000906	5VPSD36D183004949	5VPSD36D483004668	5VPSD36D783002963	5VPSD36D983005413
5VPS236D983008754	5VPSB36DX83000954	5VPSD36D183004997	5VPSD36D483004752	5VPSD36D783003014	5VPSD36D983005606
5VPS236DX83008519	5VPSB36DX83001117	5VPSD36D183005003	5VPSD36D483004766	5VPSD36D783003059	5VPSD36D983005783
5VPS236DX83008794	5VPSB36DX83001165	5VPSD36D183005079	5VPSD36D483004802	5VPSD36D783003062	5VPSD36D983005816
5VPS236L783008906	5VPSB36DX83001604	5VPSD36D183005082	5VPSD36D483004816	5VPSD36D783003126	5VPSD36D983006030
5VPSB36C283001121	5VPSB36DX83002347	5VPSD36D183005115	5VPSD36D483004850	5VPSD36D783003188	5VPSD36D983006626
5VPSB36C783001261	5VPSB36DX83002350	5VPSD36D183005437	5VPSD36D483004864	5VPSD36D783003191	5VPSD36D983008490
5VPSB36C83001125	5VPSB36DX83002915	5VPSD36D183005440	5VPSD36D483004878	5VPSD36D783003224	5VPSD36D983001337
5VPSB36D083000123	5VPSB36DX83003689	5VPSD36D183005518	5VPSD36D483004881	5VPSD36D783003269	5VPSD36DX83001368
5VPSB36D083000199	5VPSB36DX83004096	5VPSD36D183005521	5VPSD36D483004931	5VPSD36D783003272	5VPSD36D983001404
5VPSB36D083000235	5VPSB36DX83004552	5VPSD36D183005597	5VPSD36D483004945	5VPSD36D783003305	5VPSD36DX83001452
5VPSB36D083000607	5VPSB36DX83004602	5VPSD36D183005714	5VPSD36D483004959	5VPSD36D783003353	5VPSD36DX83001550
5VPSB36D083000882	5VPSB36DX83004616	5VPSD36D183006653	5VPSD36D483004976	5VPSD36D783003398	5VPSD36DX83001595
5VPSB36D083001109	5VPSB36DX83005586	5VPSD36D183008922	5VPSD36D483004993	5VPSD36D783003434	5VPSD36DX83001631
5VPSB36D083001157	5VPSB36DX83005927	5VPSD36D283001297	5VPSD36D483005013	5VPSD36D783003479	5VPSD36DX83001676
5VPSB36D083001241	5VPSB36DX83006611	5VPSD36D283001400	5VPSD36D483005061	5VPSD36D783003482	5VPSD36DX83001709
5VPSB36D083002356	5VPSB36DX83006723	5VPSD36D283001512	5VPSD36D483005139	5VPSD36D783003546	5VPSD36DX83001760
5VPSB36D083002924	5VPSB36DX83006737	5VPSD36D283001574	5VPSD36D483005142	5VPSD36D783003644	5VPSD36DX83001791
5VPSB36D083003362	5VPSB36DX83006740	5VPSD36D283001607	5VPSD36D483005335	5VPSD36D783003773	5VPSD36DX83001919
5VPSB36D083004608	5VPSB36DX83006785	5VPSD36D283001610	5VPSD36D483005416	5VPSD36D783003949	5VPSD36DX83001922
5VPSB36D083004642	5VPSB36L083002252	5VPSD36D283001655	5VPSD36D483005464	5VPSD36D783003952	5VPSD36DX83001953
5VPSB36D083005547	5VPSB36L083005166	5VPSD36D283001736	5VPSD36D483005500	5VPSD36D783003997	5VPSD36DX83002035
5VPSB36D083005550	5VPSB36L183001269	5VPSD36D283001784	5VPSD36D483005612	5VPSD36D783004003	5VPSD36DX83002083
5VPSB36D083005936	5VPSB36L183003555	5VPSD36D283001803	5VPSD36D483005738	5VPSD36D783004048	5VPSD36DX83002116
5VPSB36D083006617	5VPSB36L183003698	5VPSD36D283001901	5VPSD36D483005741	5VPSD36D783004051	5VPSD36DX83002228
5VPSB36D083006665	5VPSB36L283001538	5VPSD36D283001946	5VPSD36D483005786	5VPSD36D783004194	5VPSD36DX83002231
5VPSB36D083006746	5VPSB36L283003807	5VPSD36D283001977	5VPSD36D483005819	5VPSD36D783004230	5VPSD36DX83002276
5VPSB36D083006794	5VPSB36L283003810	5VPSD36D283002031	5VPSD36D483005822	5VPSD36D783004244	5VPSD36DX83002326
5VPSB36D183000129	5VPSB36L383001273	5VPSD36D283002059	5VPSD36D483005948	5VPSD36D783004261	5VPSD36DX83002374
5VPSB36D183000132	5VPSB36L383001886	5VPSD36D283002112	5VPSD36D483005951	5VPSD36D783004292	5VPSD36DX83002519
5VPSB36D183000163	5VPSB36L383003573	5VPSD36D283002255	5VPSD36D483006033	5VPSD36D783004311	5VPSD36DX83002522
5VPSB36D183000597	5VPSB36L383003704	5VPSD36D283002417	5VPSD36D483006422	5VPSD36D783004325	5VPSD36DX83002553
5VPSB36D183006695	5VPSB36L383003783	5VPSD36D283002420	5VPSD36D483006629	5VPSD36D783004339	5VPSD36DX83002634
5VPSB36D183000938	5VPSB36L383003816	5VPSD36D283002465	5VPSD36D483006632	5VPSD36D783004390	5VPSD36DX83002844
5VPSB36D183000972	5VPSB36L483001492	5VPSD36D283002501	5VPSD36D583001293	5VPSD36D783004406	5VPSD36DX83002939
5VPSB36D183001149	5VPSB36L483002240	5VPSD36D283002532	5VPSD36D583001309	5VPSD36D783004504	5VPSD36DX83002942
5VPSB36D183001197	5VPSB36L483003579	5VPSD36D283002613	5VPSD36D583001358	5VPSD36D783004518	5VPSD36DX83002987
5VPSB36D183001233	5VPSB36L483003582	5VPSD36D283002658	5VPSD36D583001553	5VPSD36D783004678	5VPSD36DX83002990
5VPSB36D183002365	5VPSB36L483003789	5VPSD36D283002661	5VPSD36D583001598	5VPSD36D783004762	5VPSD36DX83003038
5VPSB36D183002429	5VPSB36L483003792	5VPSD36D283002787	5VPSD36D583001634	5VPSD36D783004776	5VPSD36DX83003041
5VPSB36D183003368	5VPSB36L583002148	5VPSD36D283002823	5VPSD36D583001679	5VPSD36D783004812	5VPSD36DX83003086
5VPSB36D183003371	5VPSB36L583003798	5VPSD36D283002966	5VPSD36D583001682	5VPSD36D783004826	5VPSD36DX83003153

08/13/11
11 pages

VIN	VIN	VIN	VIN	VIN	VIN
5VPSB36D183004598	5VPSB36L683002210	5VPSD36D283003017	5VPSD36D583001763	5VPSD36D783004860	5VPSD36DX83003170
5VPSB36D183004620	5VPSB36L683003549	5VPSD36D283003020	5VPSD36D583001794	5VPSD36D783004941	5VPSD36DX83003203
5VPSB36D183005539	5VPSB36L683003552	5VPSD36D283003065	5VPSD36D583001889	5VPSD36D783004955	5VPSD36DX83003248
5VPSB36D183005542	5VPSB36L683005172	5VPSD36D283003101	5VPSD36D583001892	5VPSD36D783004972	5VPSD36DX83003251
5VPSB36D183006593	5VPSB36L783003558	5VPSD36D283003129	5VPSD36D583001925	5VPSD36D783004986	5VPSD36DX83003296
5VPSB36D183006609	5VPSB36L783003561	5VPSD36D283003132	5VPSD36D583001973	5VPSD36D783005037	5VPSD36DX83003329
5VPSB36D183006674	5VPSB36L783003804	5VPSD36D283003194	5VPSD36D583002055	5VPSD36D783005085	5VPSD36DX83003332
5VPSB36D183006755	5VPSB36L783003821	5VPSD36D283003227	5VPSD36D583002136	5VPSD36D783005118	5VPSD36DX83003413
5VPSB36D183008926	5VPSB36L883003567	5VPSD36D283003230	5VPSD36D583002198	5VPSD36D783005121	5VPSD36DX83003458
5VPSB36D283000138	5VPSB36L883003570	5VPSD36D283003275	5VPSD36D583002279	5VPSD36D783005448	5VPSD36DX83003461
5VPSB36D283000169	5VPSB36L883003701	5VPSD36D283003308	5VPSD36D583002282	5VPSD36D783005488	5VPSD36DX83003525
5VPSB36D283000172	5VPSB36L883003813	5VPSD36D283003311	5VPSD36D583002329	5VPSD36D783005491	5VPSD36DX83003606
5VPSB36D283000205	5VPSB36L983001424	5VPSD36D283003356	5VPSD36D583002332	5VPSD36D783005524	5VPSD36DX83003749
5VPSB36D283000687	5VPSB36L983002234	5VPSD36D283003437	5VPSD36D583002377	5VPSD36D783005720	5VPSD36DX83003833
5VPSB36D283000866	5VPSB36L983003576	5VPSD36D283003485	5VPSD36D583002489	5VPSD36D783005800	5VPSD36DX83003928
5VPSB36D283000902	5VPSB36L983003786	5VPSD36D283003647	5VPSD36D583002492	5VPSD36D783006009	5VPSD36DX83003931
5VPSB36D283000916	5VPSB36L983003819	5VPSD36D283003650	5VPSD36D583002525	5VPSD36D783006012	5VPSD36DX83003976
5VPSB36D283000978	5VPSB36LX83001500	5VPSD36D283003776	5VPSD36D583002556	5VPSD36D783006267	5VPSD36DX83004075
5VPSB36D283001113	5VPSB36LX83003795	5VPSD36D283003888	5VPSD36D583002637	5VPSD36D783006303	5VPSD36DX83004190
5VPSB36D283001161	5VPSB36LX83005160	5VPSD36D283003955	5VPSD36D583002640	5VPSD36D783006656	5VPSD36DX83004206
5VPSB36D283001189	5VPSD36C083001712	5VPSD36D283004006	5VPSD36D583002802	5VPSD36D783008746	5VPSD36DX83004240
5VPSB36D283001225	5VPSD36C083004741	5VPSD36D283004054	5VPSD36D583002847	5VPSD36D883001305	5VPSD36DX83004321
5VPSB36D283001547	5VPSD36C383004166	5VPSD36D283004202	5VPSD36D583002850	5VPSD36D883001384	5VPSD36DX83004335
5VPSB36D283002438	5VPSD36C483001468	5VPSD36D283004216	5VPSD36D583002945	5VPSD36D883001448	5VPSD36DX83004349
5VPSB36D283002441	5VPSD36C683001715	5VPSD36D283004278	5VPSD36D583002993	5VPSD36D883001577	5VPSD36DX83004402
5VPSB36D283003377	5VPSD36C983004558	5VPSD36D283004300	5VPSD36D583003044	5VPSD36D883001580	5VPSD36DX83004416
5VPSB36D283003380	5VPSD36D083001301	5VPSD36D283004331	5VPSD36D583003089	5VPSD36D883001613	5VPSD36DX83004447
5VPSB36D283004612	5VPSD36D083001380	5VPSD36D283004345	5VPSD36D583003092	5VPSD36D883001658	5VPSD36DX83004478
5VPSB36D283004626	5VPSD36D083001637	5VPSD36D283004359	5VPSD36D583003111	5VPSD36D883001661	5VPSD36DX83004500
5VPSB36D283005565	5VPSD36D083001640	5VPSD36D283004376	5VPSD36D583003156	5VPSD36D883001739	5VPSD36DX83004514
5VPSB36D283005825	5VPSD36D083001685	5VPSD36D283004412	5VPSD36D583003173	5VPSD36D883001742	5VPSD36DX83004528
5VPSB36D283006599	5VPSD36D083001766	5VPSD36D283004457	5VPSD36D583003206	5VPSD36D883001806	5VPSD36DX83004674
5VPSB36D283006683	5VPSD36D083001797	5VPSD36D283004474	5VPSD36D583003254	5VPSD36D883001904	5VPSD36DX83004772
5VPSB36D283006764	5VPSD36D083001895	5VPSD36D283004488	5VPSD36D583003299	5VPSD36D883001949	5VPSD36DX83004786
5VPSB36D283006800	5VPSD36D083001928	5VPSD36D283004510	5VPSD36D583003335	5VPSD36D883001997	5VPSD36DX83004822
5VPSB36D283008918	5VPSD36D083001931	5VPSD36D283004524	5VPSD36D583003464	5VPSD36D883002051	5VPSD36DX83004836
5VPSB36D383000147	5VPSD36D083001993	5VPSD36D283004538	5VPSD36D583003500	5VPSD36D883002079	5VPSD36DX83004884
5VPSB36D383000150	5VPSD36D083002027	5VPSD36D283004670	5VPSD36D583003528	5VPSD36D883002132	5VPSD36DX83004917
5VPSB36D383000178	5VPSD36D083002075	5VPSD36D283004748	5VPSD36D583003531	5VPSD36D883002258	5VPSD36DX83004951
5VPSB36D383000181	5VPSD36D083002237	5VPSD36D283004782	5VPSD36D583003626	5VPSD36D883002261	5VPSD36DX83005064
5VPSB36D383000214	5VPSD36D083002285	5VPSD36D283004796	5VPSD36D583003755	5VPSD36D883002423	5VPSD36DX83005100
5VPSB36D383000617	5VPSD36D083002335	5VPSD36D283004832	5VPSD36D583003884	5VPSD36D883002468	5VPSD36DX83005145
5VPSB36D383000679	5VPSD36D083002383	5VPSD36D283004846	5VPSD36D583003934	5VPSD36D883002471	5VPSD36DX83005338
5VPSB36D383000861	5VPSD36D083002402	5VPSD36D283004913	5VPSD36D583003979	5VPSD36D883002504	5VPSD36DX83005341
5VPSB36D383000911	5VPSD36D083002447	5VPSD36D283004927	5VPSD36D583003982	5VPSD36D883002535	5VPSD36DX83005419
5VPSB36D383001007	5VPSD36D083002450	5VPSD36D283004989	5VPSD36D583004078	5VPSD36D883002616	5VPSD36DX83005422
5VPSB36D383001038	5VPSD36D083002495	5VPSD36D283005009	5VPSD36D583004081	5VPSD36D883002664	5VPSD36DX83005467
5VPSB36D383001105	5VPSD36D083002528	5VPSD36D283005088	5VPSD36D583004212	5VPSD36D883002700	5VPSD36DX83005470
5VPSB36D383001153	5VPSD36D083002559	5VPSD36D283005091	5VPSD36D583004226	5VPSD36D883002793	5VPSD36DX83005503
5VPSB36D383001217	5VPSD36D083002643	5VPSD36D283005124	5VPSD36D583004257	5VPSD36D883002969	5VPSD36DX83005615
5VPSB36D383001556	5VPSD36D083002688	5VPSD36D283005527	5VPSD36D583004288	5VPSD36D883002972	5VPSD36DX83005663
5VPSB36D383003419	5VPSD36D083002691	5VPSD36D283005530	5VPSD36D583004307	5VPSD36D883003023	5VPSD36DX83005744
5VPSB36D383003677	5VPSD36D083002805	5VPSD36D283005690	5VPSD36D583004341	5VPSD36D883003068	5VPSD36DX83005789
5VPSB36D383003680	5VPSD36D083002853	5VPSD36D283005723	5VPSD36D583004355	5VPSD36D883003071	5VPSD36DX83005792
5VPSB36D383004554	5VPSD36D083002948	5VPSD36D283005768	5VPSD36D583004369	5VPSD36D883003104	5VPSD36DX83005954
5VPSB36D383004604	5VPSD36D083002951	5VPSD36D283005771	5VPSD36D583004372	5VPSD36D883003135	5VPSD36DX83006036
5VPSB36D383004618	5VPSD36D083002996	5VPSD36D283005804	5VPSD36D583004386	5VPSD36D883003197	5VPSD36DX83006392
5VPSB36D383005574	5VPSD36D083003002	5VPSD36D283006015	5VPSD36D583004422	5VPSD36D883003233	5VPSD36DX83006635
5VPSB36D383006689	5VPSD36D083003047	5VPSD36D283006578	5VPSD36D583004453	5VPSD36D883003278	5VPSD36L083001757
5VPSB36D383006692	5VPSD36D083003050	5VPSD36D283006581	5VPSD36D583004467	5VPSD36D883003281	5VPSD36L083002715
5VPSB36D383006708	5VPSD36D083003095	5VPSD36D283008914	5VPSD36D583004470	5VPSD36D883003314	5VPSD36L083002763
5VPSB36D383006711	5VPSD36D083003114	5VPSD36D383001289	5VPSD36D583004484	5VPSD36D883003359	5VPSD36L083003668
5VPSB36D383006773	5VPSD36D083003159	5VPSD36D383001535	5VPSD36D583004498	5VPSD36D883003443	5VPSD36L083003671
5VPSB36D483000187	5VPSD36D083003162	5VPSD36D383001583	5VPSD36D583004520	5VPSD36D883003488	5VPSD36L083003850
5VPSB36D483000612	5VPSD36D083003176	5VPSD36D383001664	5VPSD36D583004534	5VPSD36D883003491	5VPSD36L083003864
5VPSB36D483000657	5VPSD36D083003209	5VPSD36D383001700	5VPSD36D583004548	5VPSD36D883003510	5VPSD36L083003878
5VPSB36D483000691	5VPSD36D083003212	5VPSD36D383001745	5VPSD36D583004680	5VPSD36D883003653	5VPSD36L083004139

08/13/11
(1 pages)

VIN	VIN	VIN	VIN	VIN	VIN
5VPSB36D483000707	5VPSD36D083003257	5VPSD36D383001874	5VPSD36D583004744	5VPSD36D883003958	5VPSD36L083005033
5VPSB36D483000898	5VPSD36D083003260	5VPSD36D383001907	5VPSD36D583004758	5VPSD36D883003961	5VPSD36L083005193
5VPSB36D483000948	5VPSD36D083003338	5VPSD36D383001969	5VPSD36D583004792	5VPSD36D883004009	5VPSD36L083005873
5VPSB36D483001002	5VPSD36D083003341	5VPSD36D383002023	5VPSD36D583004808	5VPSD36D883004012	5VPSD36L083005906
5VPSB36D483001033	5VPSD36D083003386	5VPSD36D383002071	5VPSD36D583004842	5VPSD36D883004057	5VPSD36L183001444
5VPSB36D483001145	5VPSD36D083003422	5VPSD36D383002099	5VPSD36D583004856	5VPSD36D883004060	5VPSD36L183002562
5VPSB36D483001193	5VPSD36D083003467	5VPSD36D383002216	5VPSD36D583004887	5VPSD36D883004186	5VPSD36L183002724
5VPSB36D483001209	5VPSD36D083003470	5VPSD36D383002264	5VPSD36D583004923	5VPSD36D883004222	5VPSD36L183002769
5VPSB36D483001257	5VPSD36D083003503	5VPSD36D383002300	5VPSD36D583004937	5VPSD36D883004236	5VPSD36L183002772
5VPSB36D483002392	5VPSD36D083003534	5VPSD36D383002359	5VPSD36D583004999	5VPSD36D883004253	5VPSD36L183002903
5VPSB36D483003347	5VPSD36D083003629	5VPSD36D383002362	5VPSD36D583005005	5VPSD36D883004284	5VPSD36L183003713
5VPSB36D483003350	5VPSD36D083003632	5VPSD36D383002426	5VPSD36D583005067	5VPSD36D883004298	5VPSD36L183003839
5VPSB36D483004594	5VPSD36D083003758	5VPSD36D383002474	5VPSD36D583005070	5VPSD36D883004303	5VPSD36L183004842
5VPSB36D483004630	5VPSD36D083003761	5VPSD36D383002507	5VPSD36D583005103	5VPSD36D883004317	5VPSD36L183003856
5VPSB36D483004644	5VPSD36D083003890	5VPSD36D383002510	5VPSD36D583005148	5VPSD36D883004351	5VPSD36L183004148
5VPSB36D483005583	5VPSD36D083003937	5VPSD36D383002538	5VPSD36D583005151	5VPSD36D883004365	5VPSD36L183005025
5VPSB36D483005843	5VPSD36D083003940	5VPSD36D383002541	5VPSD36D583005389	5VPSD36D883004382	5VPSD36L183005199
5VPSB36D483005924	5VPSD36D083003985	5VPSD36D383002619	5VPSD36D583005425	5VPSD36D883004396	5VPSD36L183005882
5VPSB36D483006698	5VPSD36D083004036	5VPSD36D383002622	5VPSD36D583005473	5VPSD36D883004463	5VPSD36L283001436
5VPSB36D483006717	5VPSD36D083004084	5VPSD36D383002667	5VPSD36D583005506	5VPSD36D883004480	5VPSD36L283002733
5VPSB36D483006720	5VPSD36D083004182	5VPSD36D383002670	5VPSD36D583005618	5VPSD36D883004494	5VPSD36L283002814
5VPSB36D483006734	5VPSD36D083004196	5VPSD36D383002703	5VPSD36D583005666	5VPSD36D883004530	5VPSD36L283002909
5VPSB36D483006779	5VPSD36D083004232	5VPSD36D383002796	5VPSD36D583005702	5VPSD36D883004544	5VPSD36L283002912
5VPSB36D483006782	5VPSD36D083004246	5VPSD36D383002832	5VPSD36D583005750	5VPSD36D883004592	5VPSD36L283003719
5VPSB36D583000117	5VPSD36D083004280	5VPSD36D383002975	5VPSD36D583005795	5VPSD36D883004754	5VPSD36L283003722
5VPSB36D583000120	5VPSD36D083004294	5VPSD36D383003026	5VPSD36D583005957	5VPSD36D883004768	5VPSD36L283003848
5VPSB36D583000196	5VPSD36D083004313	5VPSD36D383003138	5VPSD36D583005960	5VPSD36D883004804	5VPSD36L283004109
5VPSB36D583000229	5VPSD36D083004327	5VPSD36D383003141	5VPSD36D583005988	5VPSD36D883004818	5VPSD36L283004112
5VPSB36D583000649	5VPSD36D083004361	5VPSD36D383003236	5VPSD36D583005991	5VPSD36D883004852	5VPSD36L283004143
5VPSB36D583000683	5VPSD36D083004392	5VPSD36D383003284	5VPSD36D583006039	5VPSD36D883004866	5VPSD36L283005017
5VPSB36D583000943	5VPSD36D083004408	5VPSD36D383003317	5VPSD36D583006042	5VPSD36D883004933	5VPSD36L283008435
5VPSB36D583000960	5VPSD36D083004490	5VPSD36D383003320	5VPSD36D583006297	5VPSD36D883004947	5VPSD36L383001364
5VPSB36D583001137	5VPSD36D083004506	5VPSD36D383003401	5VPSD36D583006638	5VPSD36D883004978	5VPSD36L383001428
5VPSB36D583001185	5VPSD36D083004540	5VPSD36D383003446	5VPSD36D583006641	5VPSD36D883004995	5VPSD36L383002207
5VPSB36D583001221	5VPSD36D083004750	5VPSD36D383003494	5VPSD36D583006845	5VPSD36D883005001	5VPSD36L383002739
5VPSB36D583001249	5VPSD36D083004764	5VPSD36D383003513	5VPSD36D583006938	5VPSD36D883005094	5VPSD36L383002742
5VPSB36D583002353	5VPSD36D083004778	5VPSD36D383003608	5VPSD36D683001285	5VPSD36D883005127	5VPSD36L383003728
5VPSB36D583002918	5VPSD36D083004800	5VPSD36D383003611	5VPSD36D683001321	5VPSD36D883005130	5VPSD36L383003731
5VPSB36D583002921	5VPSD36D083004814	5VPSD36D383003916	5VPSD36D683001349	5VPSD36D883005368	5VPSD36L383003860
5VPSB36D583004622	5VPSD36D083004828	5VPSD36D383003964	5VPSD36D683001559	5VPSD36D883005371	5VPSD36L383003874
5VPSB36D583005544	5VPSD36D083004862	5VPSD36D383004015	5VPSD36D683001562	5VPSD36D883005404	5VPSD36L383004099
5VPSB36D583005589	5VPSD36D083004909	5VPSD36D383004063	5VPSD36D683001643	5VPSD36D883005449	5VPSD36L383004118
5VPSB36D583005933	5VPSD36D083004943	5VPSD36D383004192	5VPSD36D683001688	5VPSD36D883005452	5VPSD36L383004121
5VPSB36D583006614	5VPSD36D083004957	5VPSD36D383004208	5VPSD36D683001691	5VPSD36D883005600	5VPSD36L383004135
5VPSB36D583006659	5VPSD36D083004974	5VPSD36D383004242	5VPSD36D683001769	5VPSD36D883005693	5VPSD36L383005897
5VPSB36D583006662	5VPSD36D083004991	5VPSD36D383004290	5VPSD36D683001772	5VPSD36D883005726	5VPSD36L483001440
5VPSB36D583006743	5VPSD36D083005011	5VPSD36D383004323	5VPSD36D683001934	5VPSD36D883005774	5VPSD36L483001616
5VPSB36D583006791	5VPSD36D083005039	5VPSD36D383004337	5VPSD36D683001965	5VPSD36D883005807	5VPSD36L483001910
5VPSB36D583008511	5VPSD36D083005073	5VPSD36D383004404	5VPSD36D683002095	5VPSD36D883005810	5VPSD36L483002748
5VPSB36D683000126	5VPSD36D083005106	5VPSD36D383004418	5VPSD36D683002128	5VPSD36D883005855	5VPSD36L483002751
5VPSB36D683000160	5VPSD36D083005154	5VPSD36D383004449	5VPSD36D683002243	5VPSD36D883006018	5VPSD36L483002877
5VPSB36D683000627	5VPSD36D083005347	5VPSD36D383004502	5VPSD36D683002288	5VPSD36D883006309	5VPSD36L483002880
5VPSB36D683000675	5VPSD36D083005395	5VPSD36D383004516	5VPSD36D683002291	5VPSD36D883006312	5VPSD36L483002894
5VPSB36D683000921	5VPSD36D083005428	5VPSD36D383004676	5VPSD36D683002338	5VPSD36D883006584	5VPSD36L483003737
5VPSB36D683000966	5VPSD36D083005509	5VPSD36D383004760	5VPSD36D683002341	5VPSD36D883006620	5VPSD36L483003740
5VPSB36D683000997	5VPSD36D083005512	5VPSD36D383004774	5VPSD36D683002453	5VPSD36D983001281	5VPSD36L483003852
5VPSB36D683001017	5VPSD36D083005669	5VPSD36D383004788	5VPSD36D683002498	5VPSD36D983001345	5VPSD36L483003866
5VPSB36D683001129	5VPSD36D083005672	5VPSD36D383004810	5VPSD36D683002582	5VPSD36D983001376	5VPSD36L483004127
5VPSB36D683001177	5VPSD36D083005705	5VPSD36D383004824	5VPSD36D683002694	5VPSD36D983001412	5VPSD36L483005021
5VPSB36D683001213	5VPSD36D083005798	5VPSD36D383004838	5VPSD36D683002954	5VPSD36D983001460	5VPSD36L483005214
5VPSB36D683002927	5VPSD36D083005963	5VPSD36D383004869	5VPSD36D683002999	5VPSD36D983001541	5VPSD36L583001432
5VPSB36D683002930	5VPSD36D083005994	5VPSD36D383004872	5VPSD36D683003005	5VPSD36D983001586	5VPSD36L583001754
5VPSB36D683003365	5VPSD36D083006000	5VPSD36D383004919	5VPSD36D683003053	5VPSD36D983001667	5VPSD36L583002709
5VPSB36D683004600	5VPSD36D083006045	5VPSD36D383004953	5VPSD36D683003098	5VPSD36D983001670	5VPSD36L583002712
5VPSB36D683004614	5VPSD36D083006644	5VPSD36D383004970	5VPSD36D683003117	5VPSD36D983001703	5VPSD36L583002757
5VPSB36D683005536	5VPSD36D083008930	5VPSD36D383004984	5VPSD36D683003120	5VPSD36D983001748	5VPSD36L583002760
5VPSB36D683005553	5VPSD36D083008944	5VPSD36D383005035	5VPSD36D683003165	5VPSD36D983001751	5VPSD36L583003665

08/13/21
11 pages

VIN	VIN	VIN	VIN	VIN	VIN
5VPSB36D683006587	5VPSD36D183001341	5VPSD36D383005097	5VPSD36D683003179	5VPSD36D983001877	5VPSD36L583003858
5VPSB36D683006590	5VPSD36D183001372	5VPSD36D383005133	5VPSD36D683003182	5VPSD36D983001880	5VPSD36L583005027
5VPSB36D683006606	5VPSD36D183001520	5VPSD36D383005326	5VPSD36D683003215	5VPSD36D983001913	5VPSD36L583005187
5VPSB36D683006668	5VPSD36D183001565	5VPSD36D383005410	5VPSD36D683003263	5VPSD36D983001961	5VPSD36L583005190
5VPSB36D683006671	5VPSD36D183001601	5VPSD36D383005455	5VPSD36D683003389	5VPSD36D983001989	5VPSD36L583005870
5VPSB36D683006749	5VPSD36D183001646	5VPSD36D383005603	5VPSD36D683003392	5VPSD36D983002091	5VPSD36L683002721
5VPSB36D683006752	5VPSD36D183001694	5VPSD36D383005729	5VPSD36D683003425	5VPSD36D983002107	5VPSD36L683002721
5VPSB36D683006797	5VPSD36D183001730	5VPSD36D383005732	5VPSD36D683003439	5VPSD36D983002124	5VPSD36L683002766
5VPSB36D683008503	5VPSD36D183001775	5VPSD36D383005777	5VPSD36D683003473	5VPSD36D983002219	5VPSD36L683002900
5VPSB36D783000135	5VPSD36D183001937	5VPSD36D383005780	5VPSD36D683003506	5VPSD36D983002222	5VPSD36L683003707
5VPSB36D783000166	5VPSD36D183001940	5VPSD36D383005813	5VPSD36D683003537	5VPSD36D983002267	5VPSD36L683003710
5VPSB36D783000202	5VPSD36D183001985	5VPSD36D383005858	5VPSD36D683003540	5VPSD36D983002270	5VPSD36L683003836
5VPSB36D783000622	5VPSD36D183002005	5VPSD36D383005861	5VPSD36D683003635	5VPSD36D983002303	5VPSD36L683003870
5VPSB36D783000636	5VPSD36D183002019	5VPSD36D383006279	5VPSD36D683003764	5VPSD36D983002396	5VPSD36L683004145
5VPSB36D783000653	5VPSD36D183002067	5VPSD36D383006282	5VPSD36D683003943	5VPSD36D983002431	5VPSD36L683004519
5VPSB36D783000667	5VPSD36D183002103	5VPSD36D383006380	5VPSD36D683003988	5VPSD36D983002477	5VPSD36L683004196
5VPSB36D783000703	5VPSD36D183002120	5VPSD36D383006623	5VPSD36D683003991	5VPSD36D983002480	5VPSD36L783001416
5VPSB36D783000894	5VPSD36D183002201	5VPSD36D483001317	5VPSD36D683004039	5VPSD36D983002513	5VPSD36L783002047
5VPSB36D783000992	5VPSD36D183002246	5VPSD36D483001396	5VPSD36D683004042	5VPSD36D983002544	5VPSD36L783002565
5VPSB36D783001012	5VPSD36D183002294	5VPSD36D483001544	5VPSD36D683004087	5VPSD36D983002625	5VPSD36L783002727
5VPSB36D783001043	5VPSD36D183002344	5VPSD36D483001589	5VPSD36D683004090	5VPSD36D983002673	5VPSD36L783002730
5VPSB36D783001141	5VPSD36D183002389	5VPSD36D483001592	5VPSD36D683004204	5VPSD36D983002706	5VPSD36L783002775
5VPSB36D783001169	5VPSD36D183002408	5VPSD36D483001673	5VPSD36D683004218	5VPSD36D983002799	5VPSD36L783002808
5VPSB36D783001253	5VPSD36D183002411	5VPSD36D483001706	5VPSD36D683004333	5VPSD36D983002835	5VPSD36L783002811
5VPSB36D783002399	5VPSD36D183002456	5VPSD36D483001883	5VPSD36D683004347	5VPSD36D983002933	5VPSD36L783002906
5VPSB36D783003374	5VPSD36D183002568	5VPSD36D483001916	5VPSD36D683004378	5VPSD36D983002978	5VPSD36L783003716
5VPSB36D783003410	5VPSD36D183002604	5VPSD36D483001981	5VPSD36D683004400	5VPSD36D983002981	5VPSD36L783003845
5VPSB36D783004606	5VPSD36D183002649	5VPSD36D483002001	5VPSD36D683004414	5VPSD36D983003029	5VPSD36L783003862
5VPSB36D783004640	5VPSD36D183002652	5VPSD36D483002015	5VPSD36D683004459	5VPSD36D983003032	5VPSD36L783003876
5VPSB36D783005562	5VPSD36D183002697	5VPSD36D483002063	5VPSD36D683004476	5VPSD36D983003080	5VPSD36L783004106
5VPSB36D783006596	5VPSD36D183002778	5VPSD36D483002225	5VPSD36D683004512	5VPSD36D983003144	5VPSD36L783004137
5VPSB36D783006677	5VPSD36D183002781	5VPSD36D483002273	5VPSD36D683004526	5VPSD36D983003239	5VPSD36L783005031
5VPSB36D783006680	5VPSD36D183002862	5VPSD36D483002323	5VPSD36D683004588	5VPSD36D983003242	5VPSD36L783008902
5VPSB36D783006758	5VPSD36D183002957	5VPSD36D483002368	5VPSD36D683004672	5VPSD36D983003287	5VPSD36L883002204
5VPSB36D883000175	5VPSD36D183002960	5VPSD36D483002371	5VPSD36D683004770	5VPSD36D983003290	5VPSD36L883002736
5VPSB36D883000208	5VPSD36D183003008	5VPSD36D483002435	5VPSD36D683004784	5VPSD36D983003323	5VPSD36L883002817
5VPSB36D883000211	5VPSD36D183003011	5VPSD36D483002483	5VPSD36D683004798	5VPSD36D983003404	5VPSD36L883003725
5VPSB36D883000886	5VPSD36D183003056	5VPSD36D483002516	5VPSD36D683004820	5VPSD36D983003449	5VPSD36L883003854
5VPSB36D883000984	5VPSD36D183003123	5VPSD36D483002547	5VPSD36D683004834	5VPSD36D983003452	5VPSD36L883003868
5VPSB36D883001021	5VPSD36D183003185	5VPSD36D483002550	5VPSD36D683004848	5VPSD36D983003497	5VPSD36L883004115
5VPSB36D883001133	5VPSD36D183003218	5VPSD36D483002631	5VPSD36D683004929	5VPSD36D983003516	5VPSD36L883004146
5VPSB36D883001181	5VPSD36D183003221	5VPSD36D483002676	5VPSD36D683004980	5VPSD36D983003600	5VPSD36L883005023
5VPSB36D883001228	5VPSD36D183003266	5VPSD36D483002838	5VPSD36D683005076	5VPSD36D983003614	5VPSD36L883005202
5VPSB36D883001245	5VPSD36D183003302	5VPSD36D483002841	5VPSD36D683005109	5VPSD36D983003743	5VPSD36L983001353
5VPSB36D883002380	5VPSD36D183003395	5VPSD36D483002936	5VPSD36D683005112	5VPSD36D983003824	5VPSD36L983001420
5VPSB36D883002444	5VPSD36D183003428	5VPSD36D483002984	5VPSD36D683005157	5VPSD36D983003886	5VPSD36L983002213
5VPSB36D883003383	5VPSD36D183003431	5VPSD36D483003035	5VPSD36D683005322	5VPSD36D983003919	5VPSD36L983002745
5VPSB36D883003416	5VPSD36D183003476	5VPSD36D483003083	5VPSD36D683005479	5VPSD36D983003922	5VPSD36L983002891
5VPSB36D883004596	5VPSD36D183003543	5VPSD36D483003147	5VPSD36D683005482	5VPSD36D983003967	5VPSD36L983003734
5VPSB36D883004632	5VPSD36D183003624	5VPSD36D483003150	5VPSD36D683005515	5VPSD36D983003970	5VPSD36L983003880
5VPSB36D883005568	5VPSD36D183003638	5VPSD36D483003200	5VPSD36D683005675	5VPSD36D983004018	5VPSD36L983004124
5VPSB36D883005571	5VPSD36D183003641	5VPSD36D483003245	5VPSD36D683005711	5VPSD36D983004066	5VPSD36L983004141
5VPSB36D883005828	5VPSD36D183003753	5VPSD36D483003293	5VPSD36D683005756	5VPSD36D983004200	5VPSD36L983005015
5VPSB36D883006686	5VPSD36D183003767	5VPSD36D483003326	5VPSD36D683005997	5VPSD36D983004214	5VPSD36L983005029
5VPSB36D883006705	5VPSD36D183003770	5VPSD36D483003407	5VPSD36D683006003	5VPSD36D983004228	5VPSD36L983005208
5VPSB36D883006767	5VPSD36D183003882	5VPSD36D483003455	5VPSD36D683006647	5VPSD36D983004259	5VPSD36L983005211
5VPSB36D883006770	5VPSD36D183003946	5VPSD36D483003519	5VPSD36D683006650	5VPSD36D983004309	5VPSD36LX83001619
5VPSB36D883008499	5VPSD36D183003994	5VPSD36D483003522	5VPSD36D683008429	5VPSD36D983004343	5VPSD36LX83001622
5VPSB36D983000220	5VPSD36D183004000	5VPSD36D483003603	5VPSD36D683008480	5VPSD36D983004357	5VPSD36LX83002043
5VPSB36D983000671	5VPSD36D183004045	5VPSD36D483003617	5VPSD36D783001277	5VPSD36D983004374	5VPSD36LX83002754
5VPSB36D983000699	5VPSD36D183004093	5VPSD36D483003620	5VPSD36D783001313	5VPSD36D983004388	5VPSD36LX83002897
5VPSB36D983000878	5VPSD36D183004188	5VPSD36D483003746	5VPSD36D783001392	5VPSD36D983004410	5VPSD36LX83003659
5VPSD36LX83005900	5VPSD36LX83005184	5VPSD36LX83004150	5VPSD36LX83004133	5VPSD36LX83004102	5VPSD36LX83003662
					5VPSD36LX83003872

08/13/21
(11 pages)