



2642 Hackberry Dr Goshen, IN 46526

July 30, 2008

08V-371
(2 Pages)

VIA E-MAIL
RECEIPT CONFIRMATION REQUESTED

Mr. Daniel Smith
Associate Administrator for Enforcement
National Highway Traffic Safety Administration
Attn: Recall Management Division (NVS-215)
1200 New Jersey Ave. S.E.
Washington, DC 20590

Re: Keystone RV Company
Defect and Non-Compliance Report

Dear Mr. Smith:

Keystone RV Company ("Keystone") has decided that a noncompliance with Federal Motor Vehicle Safety Standard Part 571 Standard No. 108 exists in the recreational vehicles listed below, and is furnishing notification to the National Highway Traffic Safety Administration in accordance with 49 CFR Part 573 Defect and Noncompliance Reports.

- A. Recall Population and Vehicle Identification. The recall population includes the following product brands manufactured by Keystone.

<u>Product Brand</u>	<u>Number of Vehicles</u>
2008 Everest Fifth Wheels Model 295TS Production Dates: 5/1/2007 - 4/30/2008	166
2008 - 2009 Hornet Travel Trailers and Fifth Wheels Models 26RBS, 27BHS, 29RLS, 29RBDS, 295BH Production Dates: 5/1/2007 - 6/13/2008	648
2008 - 2009 Laredo Travel Trailers and Fifth Wheels Models 265RL, 272RL, 28RBS, 29BHS, 29RLBH Production Dates: 5/1/2007 - 6/18/2008	1424
2008 - 2009 Sprinter Travel Trailers and Fifth Wheels Models 264BHS, 298FWBHS Production Dates: 5/1/2007 - 6/13/2008	647

2008 - 2009 Outback Loft Travel Trailers 105
Model 27V, 27L
Production Dates: 5/1/2007 – 6/11/2008

The total number of vehicles subject to this recall campaign is: 2990

- B. Description of Noncompliance. It has been decided that on the vehicles in the recall population the intermediate side marker lights were omitted during manufacturing. Pulling a vehicle at night without the proper side marker lighting increases the risk of other motorists not being able to see your vehicle and could possibly result in a crash.
- C. Basis for Determining that a Noncompliance Exists. The problem was discovered during an inspection at the manufacturing plant.
- D. Remedying of Noncompliance. The remedy is to install the missing intermediate side marker lights.
- E. Owner Notifications. Keystone will notify retail owners on August 15, 2008 pending NHTSA approval. A final copy of the dealer repair procedures will also be provided to NHTSA.
- F. Quarterly Reporting Requirements. Keystone will be filing quarterly reports in connection with this recall campaign.
- G. Campaign Number. Keystone's identification code for this recall is 08-110.

If you need any additional information regarding this recall campaign, please feel free to contact me at 574-537-3925.

Sincerely,

Garett Carolus
Keystone RV Company
Technical Manager