

chambers which were linked to a lot received for PACCAR build which affected chassis from May 19, 2008 through June 23, 2008.

Bendix has confirmed that grease has been removed from the assembly process of size 14 service chambers and that any product in inventory has been contained and reworked appropriately.


Description of Remedy

Kenworth and Peterbilt will replace both front air disc brakes size 14 service chambers in affected vehicles.

Identification of Recall Schedule

The Kenworth number for this campaign is "08KWA". Peterbilt's number for this campaign is "708F". Kenworth and Peterbilt will administer this recall.

Very truly yours,



Mike Walton
Counsel

cc: Patricia Wallace, NHTSA
Delia Lopez, NIITSA

MKW:kaf

E-mail: mike.walton@paccar.com