

**\* \* TECHNICAL INFORMATION NOTICE \* \***

**DATE:** April 1, 2008  
**TO:** Mitsubishi Motors Service and Parts Managers  
**RE:** Outlander Safety Recall Campaign SR-08-002  
**TIN NO.** TIN-08-SR-003

\*\*\*\*\*

Affected vehicles for Safety Recall Bulletin SR-08-002 are 2007-2008 Outlanders without power seats. (US models built before 1/28/08; Canada models built before 1/25/08). However, certain factory option groups are not subject to this recall, as they are not equipped with the subject floor harness connectors. **Do not attempt this campaign repair on unsold dealer inventory units that are not included in the affected VIN list and do not have recall operation C0802SXX on the Warranty Super Screen.**

**File under the ATIN tab in the Dealer Service Information Binder**