

GM SERVICE AND PARTS OPERATIONS
DCS2083
URGENT DISTRIBUTE IMMEDIATELY

Date: July 24, 2008

Subject: Upcoming Caterpillar Safety Recall
Fuel Pump Leak Concern

Models: 2008 Chevrolet Kodiak
2008 GMC TopKick
Equipped with Caterpillar LF6 Engine

To: Chevrolet and GMC Medium Duty Dealers

Attention: Dealer Operator, General Manager,
Sales Manager, Service Manager,
Parts Manager and Warranty Administrator

Based on information from the National Highway Traffic Safety Administration (NHTSA) website, the media may report that General Motors is aware that Caterpillar Corporation will be announcing a safety recall involving 2008 Chevrolet Kodiak and GMC TopKick vehicles equipped with Caterpillar LF6 engines.

On some of these vehicles, a fuel pump outlet check plug crack will cause fuel to spray and leak out of a crack in the plug, which may be a potential fire hazard. An engine de-rate may be experienced and a check engine lamp or an engine protection lamp may also be activated.

To correct this condition, Caterpillar will issue the Safety Recall using a Safety Product Improvement Program (the Caterpillar process used) to replace the Fuel Pump Plugs.

A total number of 361 vehicles are involved. Based on expected parts availability, Caterpillar will release the Safety Product Improvement program and customer letters in mid to late August 2008. GMVIS will not be available for this recall due to it being a Caterpillar not a GM recall.

END OF MESSAGE

GM SERVICE AND PARTS OPERATIONS