



Fleetwood Enterprises, Inc.
3030 Myers Street / Riverside, CA 92503-5527
P.O. Box 7638 / Riverside, CA 92513-7638
p: 800.322.8216 / www.fleetwoodrv.com

IMPORTANT RECALL INFORMATION #80724

August 2008

**TO: ALL FLEETWOOD DEALER PRINCIPALS,
SERVICE MANAGERS
AND PARTS MANAGERS**

**SUBJECT: RECALL CAMPAIGN #80724
2008 Terra & Fiesta Battery Control Center Wire Harness Routing**

Fleetwood Enterprises, Inc., on behalf of its subsidiary manufacturing centers located in Riverside, California, and Paxinos, Pennsylvania is requesting your assistance in conducting a voluntary recall notification campaign in accordance with the National Traffic and Motor Vehicle Safety Act.

Fleetwood Enterprises, Inc., has decided that a defect relating to motor vehicle safety exists in certain 2008 Terra and Fiesta motor homes. These motor homes were manufactured at our Riverside, California, and Paxinos, Pennsylvania manufacturing plants from September 28, 2007 through July 11, 2008.

We are notifying the owners of the affected units in order to correct the problem. A copy of the letter sent to owners is enclosed for your information.

WHAT IS THE PROBLEM?

On Terra and Fiesta model motor homes affected by this recall, the Battery Control Center (BCC) miscellaneous wire harness is routed between framing at the drivers wheel well and the front leveling jack. This routing can cause the wires to be pinched resulting in shorted or open circuits which could lead to blown fuses, house component non-operation and may result in a fire.

To correct this safety defect, it is necessary to reroute the BCC miscellaneous wire harness as described in the enclosed Recall Service Bulletin #80724.

WHAT SHOULD YOU DO?

Please check your motor home inventory and perform the repair procedure on affected units as outlined in the attached Service Bulletin #80724. It is imperative that this procedure be completed prior to the sale of the affected units so your customers will not be inconvenienced.

Owners of the above mentioned motor homes have been asked to contact their Fleetwood dealer to have the described safety defect remedied. In the event that a customer contacts you, please verify eligibility by referring to the serial number range listed in the enclosed Recall Service Bulletin #80724 prior to beginning the inspection and repairs.

Once repairs are completed, have the customer sign your dealership's Internal Repair Order and submit your request electronically through e-FDN, or you may also have the customer sign the Fleetwood Repair Order (form X-SR-042) and submit for reimbursement in accordance with Service Bulletin #80724. Customers will not be charged for these repairs.

If you have one of these vehicles in your inventory, you will be mailed a Safety Recall Notice for that specific motor home. Fleetwood is asking our dealers to make repairs to stock units on dealer lots prior to sale or lease.

Federal Law (Section 154 of the National Highway Traffic and Motor Vehicle Safety Act) of 1966 requires that: If you have received a notice of recall or failure to comply from Fleetwood or any component manufacturer, you must repair or otherwise correct the defects on vehicles remaining in your inventory according to the notification, before selling or leasing the vehicles. Any vehicle lessor receiving this recall notice must forward a copy of the notice to the lessee within ten days.

Please review this entire package with your parts and service staff to familiarize them with the step-by-step procedure and implement the Voluntary Safety Recall Campaign.

Thank you for helping Fleetwood with its continuing efforts to maintain customer satisfaction. If you have any questions, please contact your regional Fleetwood Service Center.

Sincerely,

FLEETWOOD ENTERPRISES, INC.

A handwritten signature in black ink, appearing to read "Tina Inkrote". The signature is fluid and cursive, written over a white background.

Tina Inkrote
Service Administrator
Motor Home Division

Enclosures: Recall #80724 Customer Letter
Recall #80724 Service Bulletin