

August 2008

Recall Campaign No. 08V-245, K1200 S, K1200 GT
- Front brake-disc

Dear BMW Owner:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

BMW AG has decided that a defect which relates to motor vehicle safety exists in certain 2008 BMW K1200 S and K1200 GT motorcycles. Our records indicate that you are the owner of a potentially affected motorcycle.

We sincerely apologize for any inconvenience that this may cause you.

DESCRIPTION OF DEFECT

The problem involves the mounting of the front brake-disc. Specifically, the fasteners used to secure the front brake-disc may not be long enough to ensure a secure mounting. Over time, these fasteners could loosen. If that happened, the brake disc would no longer be securely mounted.

You must have this problem corrected promptly. Failure to observe the following precautions, in conjunction with traffic and road conditions, and the rider's reactions, could increase the risk of a crash.

PRECAUTIONS FOR YOUR SAFETY

- 1. PLEASE CONTACT YOUR AUTHORIZED BMW MOTORCYCLE DEALER IMMEDIATELY TO HAVE THE NECESSARY REPAIR PERFORMED AS SOON AS POSSIBLE.**
- 2. Should you need to contact BMW Motorcycle Roadside Assistance, they can be reached at 1-877-680-2176.**
- 3. If you are not the only rider of this motorcycle, please advise all other riders of this important information.**

DESCRIPTION OF REPAIR

BMW will perform a recall campaign to remedy the affected motorcycles. Specifically, affected motorcycles will have the longer front brake disc fasteners installed, and the sensor cable rerouted.

The actual repair may take up to one half-hour; however additional time may be required depending upon the BMW dealer's scheduling and processing. This work will be performed *free of charge* by your authorized BMW motorcycle dealer.

OTHER INFORMATION

If you are no longer the owner of this motorcycle, we would appreciate you furnishing us with the name and address of the new owner using the enclosed postage-paid card.

If you are a lessor of this motorcycle, Federal Regulations require you to forward this notice to your lessee.

If you have already had this repair performed at your own expense, please see the attachment regarding possible eligibility for reimbursement.

Again, we sincerely apologize for any inconvenience this may cause you.

Should you have any questions about this campaign, please contact your authorized BMW motorcycle dealer.

We appreciate your confidence in our product, and we wish to do everything we can to retain your confidence. Should you need additional assistance, you may contact BMW Customer Relations and Services by telephone at 1-800-831-1117, or by email at CustomerService@bmwmotorcycles.com.

If the BMW motorcycle dealer is unable to remedy the defect without charge or within a reasonable period of time, you may notify the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Ave., S.E., Washington, DC 20590, call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153), or go to <http://www.safercar.gov>.

BMW OF NORTH AMERICA, LLC