

Vehicle Safety Recall Quarterly Status Report

Required per 49 CFR Part 573.7

Report Date: January 29, 2009 Calendar Quarter: 4th

Safety Recall Quarterly Report from October 1, 2008 through December 31, 2008

Manufacturer Name: American Suzuki Motor Corporation

Report Author: Ken Bush Phone: (714) 996-7040 ext. 2207

Recall Subject: 2008 Suzuki GSX-1300 Ignition Switch Wire Harness Campaign

1. NHTSA Safety Recall Campaign Number: 08V-249

Suzuki Campaign Number: 2A05

2. (a) The date notification to purchasers began: Owner notification letters were sent to all known owners of affected vehicles in the mainland U.S. on June 10, 2008.

(b) The date notification of purchasers was completed: June 10, 2008

3. The Total Number of Vehicles Involved: 9,109

The total number of vehicles involved in the subject campaign (including all items sold or distributed to purchasers, dealers, distributors, and similar entities beyond the immediate control of the manufacturer/importer).

4. (a) Total Number Inspected & Remedied: 4,381

Total number of vehicles which were inspected and/or otherwise repaired or remedied.

(b) Total Number Inspected & Not Requiring Remedy: 0

Total number of vehicles involved in the recall and inspected, but determined to not require remedial or recall repair work.

5. Vehicles Determined to be Unreachable

Number Exported: 0

Number Stolen: 0

Number Scrapped: 0

Number of Undeliverable Notification Letters: 195

Number Otherwise Unreachable: 0

Describe Other: _____