

C/O MMSC
Road 2 Km. 20.1 Candelaria Ward
Toa Baja PR 00949
PO Box 192216 San Juan PR 00919-2216
Tel. (787) 251-8715
Fax (787) 251-8700 / 251-3720

Tuesday, April 21, 2009

VIA Fax No. 1-(202)-366-7882

Ms. Kathleen DeMeter
Director, Office of Defects Investigation
National Highway Traffic Safety Administration
400 Seventh Street, S.W.
Washington D.C. 20590

Re: NHTSA Campaign No. 08V-694 – <u>Fuel Pump Sub Assembly</u> 1st Quarter Report.

Dear Ms. DeMeter:

Hyundai of Puerto Rico, C/O MMSC submits this letter for purposes of compliance with the quarterly reporting requirements of 49 C.F.R. Section 573.6. The following information is submitted for the calendar quarter ending March 30, 2009. This recall involves the following vehicles distributed by Hyundai of Puerto Rico: 2008 Hyundai Elantra vehicles with 2.0 liter Beta engines produced beginning November 5, 2007 through June 28, 2008 and equipped with fuel pumps manufactured with upper body components from a different supplier than those manufactured prior to November 5, 2007.

The following information is identified by and in the order of the paragraph headings of Section 573.6(b):

- 1. The notification campaign number assigned by NHTSA: No. 08V-694
- 2. Date of notification began and the date completed: **Notification to** customers begun and completed on February 9, 2009.
- 3. Number of vehicles involved in the campaign: 347
- 4. The number of vehicles and equipment items, which have been inspected and repaired and the number of vehicles and equipment items inspected and determined there is no need to repair:

a.	Inspected	31
b.	Repaired	31
C.	Inspected and determined	
	no need to repair	0

5. The number of vehicles determined to be unreachable for inspection due to export, theft, scrapping, failure to receive notification or other reasons (specify). The number of vehicles or items of equipment in each category shall be specified: As of March 30, 2009, the number of vehicles determined to be unreachable for inspection due to:

a.	Export	0
b.	Theft	0
Ç.	Scrapping	0
d.	Failure to receive notice	
	(Undeliverable mail) *	112

*Returned notification letters are been sent to Sales Dealer to contact owners of affected units through the sales registration address information, home/work telephone and/or cellular number.

If you require any additional information, please do not hesitate to contact the undersigned at (787) 251-8715 Ext. 2248.

Jorge A Viera Tirado Service Engineer Service Department, HDPR

C: J. Belk Arce, Legal Counselor - MMSC

J. Rivera, Parts & Service Director - MMSC

R. García, EVP. & COO. - HDPR

J. Carreras, Service Engineer - HDPR