

**RECEIVED**

By kelly.schuler at 10:17 am, Aug 30, 2010



Brian DeAscentiis  
Regulatory Activities Manager  
FUSA Government Relations  
Direct Dial: (856) 488-3465  
Fax: (856) 488-8669  
Email: bdeascentiis@subaru.com

Fuji Heavy Industries U.S.A., Inc.  
c/o Subaru of America, Inc.  
Subaru Plaza  
PO Box 6000  
Cherry Hill, NJ 08034-6000  
856-488-8500  
856-488-8669 fax

August 26, 2010  
Ref. No.: GR09-041

Ms. Kelly Schuler  
Safety Recall Analyst  
Recall Management Division  
National Highway Traffic Safety Administration  
1200 New Jersey Ave. SE  
Washington, DC 20590

RE: Subaru Recall 09V-277, 2005-2006 Subaru Baja Fuel Pump Nipple Crack (WVJ-20)

Dear Ms. Schuler,

On July 16, 2009, Subaru submitted a 573 Defect and Noncompliance Report concerning a fuel pump nipple crack on 2005 and 2006 model year Subaru Baja vehicles produced and sold in the United States. Section 573.6(c)(4) – Percentage of Vehicles Estimated to Actually Containing the Defect indicated the affected total as 15,633. Since that time, we learned that the correct total is 15,761. Please update your records accordingly.

If you have any questions or require additional information, please feel free to contact me.

Sincerely,

A handwritten signature in cursive script that reads "Brian DeAscentiis".

Brian DeAscentiis  
Regulatory Activities Manager