

BMW Group

August 5, 2009

Mr. Daniel Smith
Associate Administrator for Enforcement
National Highway Traffic Safety Administration
1200 New Jersey Ave., S.E.
Washington, DC 20590

**Re: Recall Campaign
Fuel Pump
2006 – 2008 BMW R1200 GS Motorcycles
Initial Report**

OFFICE OF DIRECTOR
REGISTRATION
2009 AUG - 1 A 9: 1
RECEIVED

Dear Mr. Smith:


This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act of 1966 and 49 CFR Part 573.

Pursuant to Section 573.6(b) of the above, we are submitting the following information pertaining to Section 573.6(c)(1), (c)(2), and (c)(5).

- 1. Manufacturer: Bayerische Motoren Werke AG (BMW AG)
Designated Agent: Jan Urbahn
BMW of North America, LLC
Woodcliff Lake, New Jersey 07677
- 2. Make: BMW
Model Year / Model: 2006 – 2008 / R1200 GS
Inclusive Dates of Manufacture: August 2006 – January 2008
- 5. The problem involves the fuel pump control unit. In isolated cases, the sealing of the control unit housing might be insufficient and, water could intrude into the control unit housing creating a humid atmosphere. If this occurred, then corrosion to the fuel pump electronics could result. Over time, if the corrosion became significant, the fuel pump could fail.

In accordance with 49 CFR 573.6(b), further information will be provided to NHTSA as it becomes available.

Sincerely,



Jan Urbahn
General Manager
Safety Engineering and Intelligent Transportation Systems

Company
BMW of North America, LLC

BMW Group Company

Mailing address
PO Box 1227
Westwood, NJ
07675-1227

Office address
300 Chestnut Ridge Road
Woodcliff Lake, NJ
07677-7731

Telephone
(201) 307-4000

Fax
(201) 571-5479

Website
bmwusa.com

