

GLOBAL SAFETY FIELD INVESTIGATIONS
DCS4179
URGENT - DISTRIBUTE IMMEDIATELY

Date: September 1, 2016

Subject: 09047D – Safety Recall
Engine Compartment Fire
Revised Warranty Transaction & Service Procedure sections

Models: 1997-2003 Buick Regal
2000-2003 Chevrolet Impala
1998-1999 Chevrolet Lumina
1998-2003 Chevrolet Monte Carlo
1998-1999 Oldsmobile Intrigue
1997-2003 Pontiac Grand Prix
Equipped with a 3.8L V6 Naturally Aspirated Engine (RPO L36 - VIN K)

To: All General Motors Dealers

This bulletin is being revised to enhance the Service Procedure with additional information to assure proper sealing of the replacement valve cover gasket, and to revise the Warranty Transaction Information section. Please discard all copies of bulletin 09047C.

Customer Letter Mailing

Customer letters are being re-mailed to owners of record to encourage completion of this recall. The customer letter mailing will begin on September 2, 2016.

END OF MESSAGE
GLOBAL SAFETY FIELD INVESTIGATIONS