



**Dealer Announcement – Baja Fuel Pump Bracket Recall – WVJ-20  
Important Update - November 2, 2009**

The Baja Fuel Pump Bracket Recall Bulletin, WVJ-20 has been revised to include instructions on exchanging the ejector pump from the old housing to the new. This procedure begins on page 9 of the revised bulletin which has been posted on the [Techinfo.Subaru.com](http://Techinfo.Subaru.com) website.

The Fuel Pump Housing Kit P/N 42029AE02A contains a large O-ring P/N 42025AE02A. This O-ring is used for the fuel filter can. There have been reports indicating the O-ring appears to be missing from the kit. It is possible that the O-ring may have slide under the carton bottom flap during shipment. Please check the packaging thoroughly if you suspect the O-ring is missing. Failure to replace the O-ring may result in engine performance issues.