



Claim # 09E-021

May 12, 2009

Dear Valued Customer

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Federal-Mogul has determined that a defect which relates to motor vehicle safety exists in certain mechanical, replacement fuel pumps. Therefore, Federal-Mogul is recalling these specific mechanical fuel pumps manufactured by our supplier.

1. Identification of equipment affected:

Federal-Mogul packaged and sold the recalled fuel pumps between August 2008 and March 2009 under the following brand names: Carter, Accu-Flow, Tru-Flow and NAPA. These mechanical fuel pumps are limited to two base part numbers. The specific part numbers being recalled, affected packaging date codes and vehicle application information are listed in the attachment to this letter.

2. Description of possible malfunction and safety evaluation:

The fuel pump diaphragm in certain production runs may have been improperly manufactured. Improperly manufactured pump diaphragm rods could cause excessive fuel pressure. With excessive fuel pressure, carburetors could flood and create a vehicle fire hazard.

3. Vehicle owner precautions:

The subject fuel pumps were manufactured for aftermarket use. Owners of these pumps should have them removed and replaced as soon as possible.

4. Owner remedy measures:

Federal-Mogul wishes to recover as many of these parts as possible. Therefore, we respectfully request that you quarantine the subject part numbers containing the affected date codes (per attachment). Date codes are located on the part number label in the lower left corner. Recalled fuel pumps from your customers also should be returned to Federal-Mogul. For reference, we have included a complete record of this recalled part number and our sales records which reflect the parts sales to you.

Once product is quarantined, please notify your local Federal-Mogul sales representative to come in to verify the product return and handle the RGA process. The subject defective part(s) must be written-up by a Federal-Mogul sales representative.

The return of the part(s) will be at no cost to you. Upon return of this part(s), your account will be credited for the part(s). For replacement of recalled product, you will need to order the appropriate stock number from Federal-Mogul customer service.

Parts stores that purchased these items should return them to their servicing warehouse distributor for credit.

If the part is suspected of having been installed on a vehicle, Federal-Mogul will pay for inspection and, if the part is covered by the recall, replacement, as well as shipping charges. In order to qualify for this reimbursement, the subject recalled part(s) must be written-up and routed through the normal labor claim procedure including appropriate receipts.

No recalled fuel pumps currently in your inventory may be sold as it is a violation of federal law for a dealer to sell a recalled item of motor vehicle equipment.

5. Owner complaint process

The owner of a vehicle with a recalled fuel pump may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE, Washington, D.C. 20590 or call the toll-free Auto Safety Hotline at 1-888-327-4236 (TTY: 1-800-429-9153), or go to <http://www.safercar.gov>, if the owner believes that Federal-Mogul has failed or is unable to remedy without charge the condition outlined above within a reasonable time.

Please review the above information and contact your sales representative or call 1-877-489-6659 with any questions. Although this recall will be continuing, please process returns of product currently in your inventory by June 15, 2009.

Our commitment to product quality is at the forefront of all we do at Federal-Mogul. We apologize for any inconvenience this voluntary recall may cause. We know, however, that you share our concern for vehicle safety. We appreciate your continuing assistance in this matter.

Sincerely,

A handwritten signature in black ink, appearing to read 'R. King', with a long horizontal flourish extending to the right.

Raymond King
Director, Marketing, Global Aftermarket Underhood Products
Federal-Mogul

Enclosure