

SAFETY RECALL H36 STEERING DRAG LINK INNER JOINT AND DAMPER BRACKET

Doar: (Name)

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Chrysler has decided that a defect, which relates to motor vehicle safety, exists in some 2008 and 2009 model year Dodge trucks.

The problem is...

Also the steering damper bracket at the tie rod tube may loosen. This could allow the bracket to slide on the tube and may cause increased vehicle turning radius.

What your dealer will do...

Chrysler will repair your vehicle free of charge (parts and labor). To do this, your dealer will replace the steering drag link inner joint and inspect, and replace if necessary, the steering damper bracket. The work will take about 1 hour to complete. However, additional time may be necessary depending on service schedules.

What you must do to ensure your safety... Simply contact your dealer right away to schedule a service appointment. Ask the dealer to hold the parts for your vehicle or to order them before your appointment. Remember to bring this letter with you to your dealer.

If you need help...

If you have questions or concerns which your dealer is unable to resolve, please contact Chrysler at 1-800-853-1403.

If you have already experienced this condition and have paid to have it repaired, you may send your original receipts and/or other adequate proof of payment to the following address for reimbursement: Chrysler Recall Customer Assistance, P.O. Box 21-8007, Auburn Hills, MI 48321-8007, Attention: Reimbursement.

If your dealer fails or is unable to remedy this defect without charge and within a reasonable time, you may submit a written complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Ave., S.E., Washington, DC 20590, or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to http://www.safercar.gov.

We're sorry for any inconvenience, but we are sincerely concerned about your safety. Thank you for your attention to this important matter.

Customer Services Field Operations
Chrysler
Notification Code H36

Note to lessors receiving this recall: Federal regulation requires that you forward this recall notice to the lessee within 10 days.