



April 2011

Dear General Motors Customer:

General Motors is very interested in your safety and continued satisfaction with your vehicle. Our records show that although your 1997 model year Buick Regal / Pontiac Grand Prix model vehicle is subject to an important safety recall, the necessary repairs have not been made. Therefore, we are sending an additional notification of this important safety recall. Please follow the instructions below to address this important matter.

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

General Motors has decided that a defect, which relates to motor vehicle safety, exists in **certain** 1997 model year Buick Regal / Pontiac Grand Prix model vehicles, equipped with a 3.8L V6 naturally aspirated engine. As a result, GM is conducting a safety recall. We apologize for this inconvenience. However, we are concerned about your safety and continued satisfaction with our products.

I M P O R T A N T

- Your vehicle is involved in safety recall 09047.
- Schedule an appointment with your GM dealer.
- This service will be performed for you at **no charge**.

Why is your vehicle being recalled?

An underhood fire may be caused by drops of engine oil, from seepage or spillage, being deposited on the exhaust manifold through hard braking. If the manifold is hot enough, the oil may ignite into a small flame and, in some instances, the fire may spread to the plastic spark plug wire channel and beyond. If this occurs, there could be a fire in your vehicle and nearby property.

What will we do?

Your GM dealer will replace the spark plug wire channel with new spark plug wire retainers. This service will be performed for you at **no charge**. Because of service scheduling requirements, it is likely that your dealer will need your vehicle longer than the actual service correction time of approximately 15 minutes.

What should you do?

You should contact your GM dealer to arrange a service appointment as soon as possible. Bring the enclosed customer reply form with you when you visit your dealer. The form identifies the repairs required. If you no longer own this vehicle, please let us know by completing the form and mailing it back to us.

There are two very important precautions you should take before your vehicle is serviced:

- We strongly recommend you not park your vehicle in a garage, car port, or other structure.
- If you notice a burning odor, you should have your GM dealer inspect your vehicle immediately. The dealer will inspect your vehicle without charge.

Do you have questions?

If you have questions or concerns that your dealer is unable to resolve, please contact the appropriate Customer Assistance Center at the number listed below. More information about this recall can be found at the Owner Center at MyGMLink, <http://www.gm.com/recall>.

Division	Number	Text Telephones (TTY)
Buick	1-866-608-8080	1-800-832-8425
Chevrolet	1-800-630-2438	1-800-833-2438
Oldsmobile	1-800-630-6537	1-800-833-6537
Pontiac	1-800-620-7668	1-800-833-7668
Guam	1-671-648-8450	
Puerto Rico – English	1-800-496-9992	
Puerto Rico – Español	1-800-496-9993	
Virgin Islands	1-800-496-9994	

If after contacting your dealer and the Customer Assistance Center, you are still not satisfied we have done our best to remedy this condition without charge and within a reasonable time, you may wish to write the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE, Washington DC 20590, or call the toll-free Vehicle Safety Hotline at 1.888.327.4236 (TTY 1.800.424.9153), or go to <http://www.safercar.gov>.

Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

Jim Moloney
General Director,
Customer and Relationship Services

Enclosure
09047