



Date

Name

Address

City, St, Zip

VIN#

Subject: Ducati Motorcycles:

M.Y.'09 1198 S, M.Y. '09 1098 R, M.Y.'10 F1098S Streetfighter

Dealer Bulletin: RCL-09-005

NHTSA Campaign I.D. Number: 09V-381

Transport Canada Safety Recall I.D. Number: 09-274

Summary of Procedure: On the above referenced models it is necessary to inspect and, on motorcycles requiring repair, replace and reposition the fuel hose clamp.

Dear Ducati Owner,

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Ducati Motor Holding S.P.A. has decided that a defect that relates to motor vehicle safety exists in certain model year '09 1198 S, M.Y. '09 1098 R, M.Y.'10 F1098S Streetfighter motorcycles. Our records indicate that you are the owner of a Ducati motorcycle affected by this safety recall campaign. Please take the time to read this letter and help us take the appropriate steps to ensure that your vehicle is operating properly.

Ducati Motor Holding S.p.A. has determined that the motorcycle may have a fuel hose that may become disconnected from the fuel pump assembly which could result in damage to the motorcycle and a potential hazard to the rider. Any loss of fuel pressure may lead to loss of functionality of the motorcycle, and thereby increase the risk of a crash.

To correct this condition, your authorized Ducati dealer will inspect and, if required, replace and reposition the fuel hose retaining clamp at no cost to you for parts and labor.

We request that you contact your authorized Ducati dealer and schedule an appointment, so that the required service can be performed without delay. To locate your nearest authorized Ducati dealer, please go to www.ducatiusa.com and select the "dealer locator" or you may call toll free from the U.S. 800-231-6696. Your dealer can complete the required service in under two hours, if you have an appointment. If your dealer has a number of vehicles awaiting service, additional time may be required.



Precautions - If you are not the only rider of this motorcycle, please advise all other riders of this important information. You may continue to ride this motorcycle; however, if you chose to do so, do not leave this problem unattended.

Service Problem Help:

If you believe that your dealer has failed or is unable to perform the service within a reasonable period of time, please write to:

Ducati North America, Inc.
Attn: Customer Service
10443 Bandle Drive
Cupertino, CA 95014

If you still cannot obtain satisfaction, you may file a complaint with the appropriate Administrator listed below:

USA Customers:

National Highway Traffic Safety Administration
1200 New Jersey Avenue, SE
Washington, D.C. 20590
Or call toll-free hotline at 1-888-327-4236
(TTY 1- 800-424-9153), or go to [HTTP://WWW.SAFERCAR.GOV](http://www.safercar.gov).

Canadian Customers:

Canada Motor Vehicle Safety
And Motor Vehicle Regulation Office
Telephone: (613) 993-9542

TREADACT CUSTOMER REIMBURSEMENT PLAN

Ducati North America, Inc.

If you have paid for the repair described in the attached letter, and you would like to be considered for reimbursement, please contact your authorized Ducati dealer. Expenses from repair facilities outside of the authorized Ducati dealer network will be considered; however, the procedure must meet Ducati North America's standards and use Ducati original replacement parts.

Your authorized Ducati retailer will request a copy of your owner notification letter, as well as, a copy of your previously paid invoice. They inspect the vehicle, if still in your possession, prior to submitting a claim on your behalf to Ducati North America, Inc. for reimbursement.

Please note the following:

Only a repair subject of this safety recall campaign is reimbursable. Ducati North America, Inc will not reimburse consequential expenses such as towing, rental, accommodations, and damage repairs.

Ducati North America, Inc. will not reimburse for prior repairs that did not utilize original Ducati parts.



We recommend that your authorized Ducati dealer be your primary contact on this issue. We anticipate that your authorized Ducati dealer will be able to answer any questions that you may have regarding your qualifications for reimbursement of a previous repair; however, our Customer Relations Dept. may be contacted at 408-253-0499 for any special assistance required.

We regret any inconvenience to you from this action; however, your safety and satisfaction are important to us. We request that you bring your Ducati motorcycle to your nearest authorized Ducati dealer at your earliest convenience.

Thank you for riding Ducati.

Sincerely,

Ducati North America
Service Department