



March 15, 2010

SAFETY RECALL NOTICE

VOLUNTARY SAFETY RECALL CAMPAIGN # 09V-487

Dear UD Truck Owner:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Nissan Diesel America, Inc. has determined that specific 2007 and 2008 Model Year UD3300 model vehicles modified with dual steering for street sweeper use fail to comply with the requirements of Federal Motor Vehicle Safety Standard No. 121, "Air Brake Systems". The vehicle identified on the enclosed "AUTHORIZATION FOR RECALL SERVICE" card fits this description and our records list you as the owner of this vehicle.

Brake Actuation and Release Timing recertification was not performed on these vehicles by the intermediate manufacturer, Pioneer Drive, LLC, during installation of the dual steering system. Operation of a vehicle with incorrect air brake apply/release timing may result in reduced braking performance which could increase the risk of vehicle crash.

As a remedy the following will be performed.

- The supply and delivery tubing between the Right and Left Foot Valves will be changed from 1/2" to 3/8" diameter for the rear brake system.
- The existing Quick Release Valve (QR-1) for the front brake system will be replaced with an R-12 Relay Valve with a 1/2" air supply line.
- The rear brake QR-1 Valve will be relocated forward to inside the right frame rail adjacent to the rear engine cross member. The 1/2" air line between the Brake Foot Valves, QR-1 Valve and rear Brake Relay Valve will be changed to a 3/8" air line.
- The 90° fittings will be replaced with straight fittings in the delivery tubing between the Foot Valves for both front and rear brake systems.
- Rear service brake hoses with 45° fittings will be installed.

Please contact an authorized UD Truck Dealer as soon as possible to schedule an appointment to have this recall performed at no charge to you. It is estimated that approximately 2 days will be required to complete the repairs.

Federal regulations require that all vehicle lessors must notify all lessees within ten (10) days of receiving this notice.

IMPORTANT: We would appreciate your bringing the "AUTHORIZATION FOR RECALL SERVICE" card with you to the UD Truck Dealer at the time of your repair appointment. If you do not have the "AUTHORIZATION FOR RECALL SERVICE" card, please provide the Vehicle Identification Number (VIN) to the UD Truck Dealer when scheduling your appointment to verify that your vehicle requires this recall service.

You may be entitled to reimbursement of costs to repair a previous failure related to this recall. If you believe that you have paid for previous repairs related to this recall, please contact Nissan Diesel America, Inc. at (972) 756 - 5523.

If you no longer own or possess this vehicle, please fill in the requested information on the enclosed postage prepaid "AUTHORIZATION FOR RECALL SERVICE" card and return it to the Nissan Diesel America, Inc. Service Operations Department. This will allow proper identification and notification to the current owner of this vehicle.

You may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Ave., S.E., Washington, DC 20590 or call the toll free Vehicle Safety Hotline at 1-888 -327- 4236 (TTY 1-800-424-9153); or go to <http://www.safercar.gov>, if you believe that either Nissan Diesel America, Inc. or the UD Truck Dealer has failed or is unable to repair your vehicle without charge.

We regret any inconvenience this recall may have caused. If you have any questions regarding this recall, you may call the Nissan Diesel America, Inc. Service Operations Department at (972) 756 - 5523.

Sincerely,
NISSAN DIESEL AMERICA, INC.

C O R P O R A T E O F F I C E S

P.O. Box 152034, Irving, Texas 75015-2034 • 5930 West Campus Circle Drive, Irving, Texas 75063

Telephone 972-756-5500 • Fax 972-550-1255

<http://www.udtrucks.com>