

90L/9LG – Potential Floor Mat Interference with Accelerator Pedal (Remedy Launch Date)

Safety Recall No. (09V-388 and 10V-023)	Phase	Model	NHTSA Recall No.	Owner Letter Start
90L (Toyota)	1	2007 – 2010 Camry/Camry HV (Denso)	09V-388	02/16/2010
	2	2007 – 2010 Camry (CTS)	09V-388	02/16/2010
	3	2005 – 2010 Avalon	09V-388	03/01/2010
	4	2008 – 2010 Highlander HV	10V-023	03/30/2010
	5	2004 – 2009 Prius	09V-388	04/23/2010
	6	2008 – 2010 Highlander (Non-Hybrid), 2007 – 2010 Tundra	10V-023 (Highlander) 09V-388 (Tundra)	04/30/2010 (Highlander) 05/05/2010 (Tundra)
	7	2009 – 2010 Corolla, 2009 – 2010 Matrix	10V-023	06/21/2010
	8	2007 – 2010 Camry (Sport Pedal)	09V-388	7/16/2010
	9	2005 – 2010 Tacoma, 2009 – 2010 Venza	09V-3883 (Tacoma) 10V-02 (Venza)	08/02/2010 (Tacoma) 7/28/2010 (Venza)
9LG (Lexus)	1	2007 – 2010 Lexus ES	09V-388	12/31/2009
	2	2006 – 2010 Lexus IS	09V-388	4/23/2010

90L: