



Mitsubishi Motors North America, Inc.

6400 Katella Avenue
Cypress, CA 90630
Tel: 714-372-6000
www.mitsubishicars.com

April 13, 2011

Kathleen DeMeter, Esq.
Director, Office of Defects Investigation
NHTSA – NVS-200, RM W46-421
1200 New Jersey Ave. SE
Washington, D.C. 20590

Subject: Quarterly Campaign Progress Report – 1st Quarter 2011

Dear Ms. DeMeter:

Attached is the Quarterly Campaign Progress Report prepared in accordance with 49 CFR Part 573.7 for the calendar quarter January 1 through March 31, 2011 (1st Quarter 2011).

If you have any questions concerning this report, please do not hesitate to contact me directly during normal business hours.

Sincerely,

A handwritten signature in cursive script that reads "Sharon Kaplan".

Sharon Kaplan
Sr. Specialist, Technical Compliance
Mitsubishi Motors North America, Inc.
Telephone: (714) 372-6148
Fax: (714) 934-4202
E-mail: skkaplan@mmsa.com

cc: Kelly Schuler (Email)

Enclosure



MMNA 1st Quarter 2011
Safety Recall Campaign Progress Report

NHTSA Recall Number	MMNA Recall Number	Campaign Name	Owner Notification Start	Owner Notification End	Total Number of Vehicles Involved	Number Vehicles inspected and Repaired	Number Vehicles inspected not needing Repair	Vehicles Exported	Vehicles Stolen	Vehicles Scrapped	Notification Undeliverable	Sold or Traded	Quarters Reported
09V435	SR-09-005	Lancer/Lancer Evolution SRS Front Impact Sensor	27-Nov-09	27-Nov-09	29,779	20,056	NA	6	2	330	854	74	6
10V066	SR-10-001	Galant A/T Oil Cooler Pipe	22-Mar-10	22-Mar-10	2,307	680	1,360	0	0	6	6	1	4
10V065	SR-10-002	2004 Endeavor Fuel Filler Pipe	6-Jul-10	6-Jul-10	35,456	5,614	4,428	1	1	264	1,654	847	4
NOTE: SR-10-002 is superceded by SR-11-001, which expands the affected model years.													
10V514	SR-10-003	HVAC Controller Replacement	7-Dec-10	7-Dec-10	19,402	6,102	NA	0	0	44	415	6	2
10V065 (expanded)	SR-11-001	2004-2010 Endeavor Fuel Filler Pipe (supercedes SR-10-002)	28-Feb-11	28-Feb-11	64,441	7,600 *	NA	6	0	126	1,890	56	1

* 1,640 anti-corrosion coating & protector installation + 5,960 pipe replacements