



Warranty claims should be submitted quoting the Program Code 'P018' together with the Option Code 'X'. It will be necessary to enter the relevant SRO and, if necessary, the parts used. Where the windshield is installed as a sublet repair, please quote 'ZZZ001' as the Sundry Code and claim the sublet invoice value. In the case of sublet repairs, please follow the required Warranty policy found in the *Warranty Policies & Procedures Manual* (InfoTrail). The drive in / drive out allowance can only be claimed if the vehicle is brought back into the workshop for this action alone to be undertaken.

Program Code	Option Code	Description	SRO	Time (hours)
P018	X	Rear windshield bonding inspection only (vehicle OK)	05.10.10	0.10
P018	X	Check rear windshield and replace front windshield	76.81.01	3.40
P018	X	Drive in / Drive out	02.02.02	0.20

Normal warranty policy and procedures apply.

REPAIR PROCEDURE

INSPECT TAILGATE GLASS

1. Open tailgate.




NOTE: Global Technical Reference (GTR) lookup sequence is as follows:

GTR Home > NAS > LM - New Range Rover > Service Information > 2009 > Workshop Manual > 5: Body and Paint > 501: Body and Paint > 501-05: Interior Trim and Ornamentation

2. Refer to Workshop Manual (GTR) section 501-05: Interior Trim and Ornamentation and remove the liftgate upper trim panel.
3. Inspect the area along the bead adjacent to the window wiper spindle grommet for a 'clear primer witness mark'. (Figure 1)
 - If a 'clear primer witness mark' is present, refer to Workshop Manual (GTR) section 501-05: Interior Trim and Ornamentation and install the liftgate upper trim panel and release vehicle to customer.
 - If no 'clear primer witness mark' is present, continue to REPLACE FRONT WINDSHIELD GLASS.

Figure 1



REPLACE FRONT WINDSHIELD GLASS



NOTE: If the front windshield is damaged upon removal, install a new windshield.

If the front windshield is not damaged upon removal, install the original windshield.



NOTE: Global Technical Reference (GTR) lookup sequence is as follows:

GTR Home > NAS > LM - New Range Rover > Service Information > 2009 > Workshop Manual > 5: Body and Paint > 501: Body and Paint > 501-11: Glass, Frames, and Mechanisms

1. Refer to Workshop Manual (GTR) section 501-11 (76.81.01) and remove / install or, if necessary, replace the front windshield glass.



RECALL P018

Affected VIN List - Canada

VIN	RETAILER CODE	RETAILER NAME
9A305948	0503	Budds' Imported Cars
9A305651	0509	Decarie Motors
9A305865	0502	Land Rover Edmonton
9A305548	0519	Land Rover Richmond
9A305888	0519	Land Rover Richmond
9A305961	0519	Land Rover Richmond
9A305550	0533	Land Rover Saskatoon
9A305910	0526	Land Rover Thornhill
9A305902	0541	Land Rover Toronto (2004)
9A305941	0541	Land Rover Toronto (2004)
9A305774	0508	Land Rover Vancouver
9A305866	0508	Land Rover Vancouver



RECALL P018 Affected VIN List - USA

VIN	RETAILER CODE	RETAILER NAME
9A306052	0126	Dimmitt Land Rover
9A306030	0239	Land Rover Asheville
9A306036	0239	Land Rover Asheville
9A305915	0234	Land Rover Austin
9A305699	0159	Land Rover Cherry Hill
9A306055	0290	Land Rover Columbia
9A306103	0290	Land Rover Columbia
9A305786	0136	Land Rover Dallas
9A305701	0232	Land Rover Farmington Hills
9A305726	0122	Land Rover Glen Cove
9A305992	0122	Land Rover Glen Cove
9A306010	0201	Land Rover Greenville
9A306031	0285	Land Rover Larchmont/New Rochelle
9A306053	0282	Land Rover Manhattan
9A306509	0313	Land Rover Mission Viejo
9A305575	0148	Land Rover Monmouth
9A306059	0131	Land Rover North Dade
9A305634	0115	Land Rover Palm Beach
9A305655	0115	Land Rover Palm Beach

VIN	RETAILER CODE	RETAILER NAME
9A305443	0110	Land Rover Paramus
9A305675	0110	Land Rover Paramus
9A305864	0110	Land Rover Paramus
9A305883	0110	Land Rover Paramus
9A305964	0110	Land Rover Paramus
9A305981	0110	Land Rover Paramus
9A306042	0110	Land Rover Paramus
9A306016	0121	Land Rover Parsippany
9A306028	0121	Land Rover Parsippany
9A306033	0121	Land Rover Parsippany
9A305451	0178	Land Rover Pasadena
9A305454	0284	Land Rover Roaring Fork
9A306023	0253	Land Rover South Dade
9A306062	0253	Land Rover South Dade
9A306091	0253	Land Rover South Dade
9A305430	0358	Land Rover Sudbury
9A305462	0296	Land Rover Tysons Corner
9A305913	0338	Land Rover Waukesha
9A305619	0171	Land Rover West Ashley
9A306507	0225	Land Rover Winnetka
9A305716	0111	Plaza Land Rover St. Louis