



May 20, 2010

MR. KENNETH M. BUSH ASSOCIATE DIRECTOR GOVERNMENT RELATIONS AMERICAN SUZUKI MOTOR CORPORATION PO BOX 1100 BREA, CA 92822-1100 NVS-215dgl 10V-213

SUBJECT: LOWER CONTROL LINK ASSEMBLY

DEAR MR. BUSH:

This letter serves to acknowledge American Suzuki Motor Corporation's notification to the National Highway Traffic Safety Administration (NHTSA) of a defect in the vehicles listed below for which a safety recall campaign will be conducted pursuant to Federal law.

Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

SUZUKI/EQUATOR/2010

NHTSA Campaign Number: 10V-213

Mfg's Report Date: May 12, 2010

Components: SUSPENSION: FRONT: CONTROL ARM

Potential Number of Units Affected: 582

Summary:

SUZUKI IS RECALLING CERTAIN MODEL YEAR 2010 EQUATOR PICKUP TRUCKS MANUFACTURED FROM NOVEMBER 20, 2009 THROUGH MARCH 3, 2010. THE LOWER CONTROL LINK BUSHING COLLARS, LOCATED IN THE FRONT SUSPENSION, MAY CONTAIN WELDS THAT DO NOT MEET STRENGTH SPECIFICATIONS. IF A COLLAR WELD SEPARATES, IT MAY CHANGE THE WHEEL ALIGNMENT, POTENTIALLY ALLOWING THE VEHICLE HANDLING CHARACTERISTICS TO DETERIORATE.

Consequence:

THIS COULD CAUSE THE DRIVER TO HAVE DIFFICULTY CONTROLLING THE VEHICLE WHICH COULD RESULT IN A CRASH.

Remedy:

DEALERS WILL INSPECT, AND IF NECESSARY REPLACE, ONE OR BOTH LOWER CONTROL LINKS ON THE VEHICLE FREE OF CHARGE. THE SAFETY RECALL IS EXPECTED TO BEGIN ON OR BEFORE MAY 24, 2010. OWNERS MAY CONTACT SUZUKI AT 1-800-934-0934.

Notes:

CUSTOMERS MAY CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION'S VEHICLE SAFETY HOTLINE AT 1-888-327-4236 (TTY: 1-800-424-9153); OR GO TO HTTP://WWW.SAFERCAR.GOV.

The information in your defect report appears to satisfy the requirements of 49 CFR 573.6.

We have reviewed your proposed owner letter and it meets the requirements of 49 CFR Part 577.

Please provide the following additional information and be reminded of the following requirements:

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within 30 days after the close of the calendar quarter in which the campaign was initiated. Thereafter, quarterly reports will be due on or before 30 days after close of the calendar quarter.

Your contact for this recall will be Delia Lopez who may be reached by phone at 202-366-9525, or by email at Delia.lopez@dot.gov, or through the office email at RMD.ODI@dot.gov. We look forward to working with you toward a successful completion of this recall campaign.

Sincerely,

George H. Person

Chief, Recall Management Division Office of Defects Investigation

Enforcement