

Publish Date: April 26, 2010
From: Technical Service
Expiration Date: May 10, 2010

DCSnet Message
Important

Subject: **Safety Recall Campaign - 2010 X5 M SAV - Front Side
Marker Lamps**

We have advised NHTSA that a recall will be conducted for the Side Marker Lamps for the 2010 BMW X5 M SAV.

No accidents or injuries have been reported.

Make: BMW

<u>Model Year/Model</u>	<u>Inclusive Dates of manufacture</u>
2010/X5 M SAV	July 1, 2009 – January 25, 2010

The number of units affected is approximately 735.

The problem involves the side marker lamps. Affected vehicles were equipped with side marker lamps, but not the power supply cables leading to the lamps. As a result, the side marker lamps do not illuminate. Therefore, affected vehicles do not conform to FMVSS 108.

Further information will be forthcoming as soon as it is available.

Attached is a Q&A for your use.

The NHTSA Recall Identifier is "10V-152".

Attachments:



Recipients:

BMW SAV (Light Trucks), All Offerings, All Regions, All Areas, Service, All