



Fleetwood RV, Inc.  
1010 Commerce Dr.  
Decatur, Indiana 46733  
P: (800) 322-8216 / www.fleetwoodrv.com

April 27, 2010

Mr. Daniel C. Smith  
Associate Administrator for Enforcement  
National Highway Traffic Safety Administration  
1200 New Jersey Ave, SE  
Washington, DC 20590

Re: Non-Compliance Report **AMENDMENT**

Dear Mr. Smith:

On April 20, 2010, Fleetwood RV, Inc. decided that a non-compliance to the requirements of Part 567 "Certification" exists in certain motor homes as listed below, and is furnishing notification to the National Highway Traffic Safety Administration in accordance with 49 CFR Part 573 Defect and Non-compliance reports.

The following is the information required by 49 CFR Part 573:

- This report was prepared on April 23, 2010.
  - Fleetwood RV has assigned **10420FRV** as an identification code to this recall.
- (1) The affected motor homes were manufactured by the following wholly owned subsidiary of Fleetwood RV, Inc.

Fleetwood RV, Inc. #44  
1031 U.S. 224 E  
Decatur, Indiana 46733

The agency should contact the following individual with respect to this recall:

Steve Heim  
National Owner Relations Manager  
1010 Commerce Dr., P.O. Box 1007  
Decatur, Indiana 46733  
Telephone: 260-724-5720  
E-mail: steve.heim@fleetwoodrv.com

- (2) The vehicles involved in the recall are certain model year 2010 Bounder Classic Model 30T and Encounter Models 28MS, 30SA & 32BH Class A motor homes manufactured February 26, 2010 through March 29, 2010.

The March 29, 2010 date coincides with corrected Federal Certification Tags being applied to the motor homes during production.

These motor homes were built with a Fleetwood RV identification number range of:


Bounder Classic	738TA4405328 through 738TA4405331
Encounter	785MA4405034 through 785MA4405314
Encounter	785SA4405098 through 785SA4405115
Encounter	785BA4405116 through 785BA4405147

- (3) Fleetwood RV reports approximately 86 as the number of model year 2010 Bounder Classic Model 30T and Encounter Models 28MS, 30SA & 32BH Class A model motor homes containing the non-compliance.

- (4) Fleetwood RV estimates that 100% of the affected model year 2010 Bounder Classic Model 30T and Encounter Models 28MS, 30SA & 32BH Class A model motor homes contain the non-compliance.
- (5) On motor homes affected by this recall, the Federal Certification Tag figures related to the front and rear tire pressure rating are incorrect. The correct front tire pressure rating is 95 PSI and the rear tire pressure rating is 100 PSI.
- (6) Not applicable.
- (7) Fleetwood RV began an investigation in March 2010 after discovering the error.
- (8) Fleetwood RV will mail correct Federal Certification Tags to dealers and owners of record. We will ask that they deface the original Federal Certification Tag and replace it with the new, serial number specific tag. Owners who are not comfortable installing these labels will be asked to contact a Fleetwood RV dealer to have this service performed at no charge.
- (9) Fleetwood RV intends to conduct a dealer notification by e-mail in April 2010.  
  
Fleetwood RV intends to conduct a customer notification in April 2010.  
  
Fleetwood RV does not foresee any problems with implementing this voluntary recall campaign.
- (10) Copies of subsequent correspondence will be submitted to the NHTSA within five (5) working days of distribution. This correspondence will include:
  - I) Letter of dealer notification
  - II) Letter of customer notification
  - III) Service Bulletin

A draft of these documents will be forthcoming for your review. If additional information is required, please contact Cindy Hodge who can be reached by phone at (260) 724-5739 or by e-mail at [cynthia.hodge@fleetwoodrv.com](mailto:cynthia.hodge@fleetwoodrv.com).

Sincerely,



Steve L. Heim  
National Owner Relations Manager