

**RECEIVED**  
By Recall Mgt Div. at 3:53 pm, May 24, 2010

**DAIMLER**

10V-183  
(1 page)

Daimler Trucks North America  
Nasser Zamani  
Senior Manager  
Compliance and Regulatory Affairs

May 20, 2010

Dan Smith  
Associate Administrator for Vehicle Safety  
National Highway Traffic Safety Administration  
1200 New Jersey Avenue S.E.  
Washington D.C. 20590

**Re: Defect Information Report – Supplemental Report No. 1  
10V-183, Dash Heater Actuator – School Bus Portion**

Mr. Smith,

In accordance with Part 573 of Title 49 of the Code of Federal Regulations, Daimler Trucks North America LLC herewith submits supplemental defect information to amend the remedy program specified in its original defect report dated April 30, 2010.

**(c)(8) (i) Remedial program:** The dash heater actuator will be replaced with a more robust actuator. Until a replacement actuator is available, customers are advised to disconnect the power source from the existing actuator. Repairs will be performed by Thomas Built dealerships and Direct Warranty customers, i.e., customers approved by Thomas Built to do their own warranty repairs

Please contact me if you have any questions.

Sincerely yours,



Nasser Zamani

Cc: Michael Mason, CAL-OSHA  
Via Email

A Daimler Company

Daimler Trucks North America LLC  
4747 N. Channel Avenue  
Portland OR 97217-7699  
503-745-6910 Phone  
503-745-6544 Fax  
Nasser.Zamani@Daimler.com