



10V445
(2 Pages)

3701 Johnson Road • Chanute, KS 66720 • Phone 620-431-2088 • Main Office Fax 620-431-2513 • Sales Dept. Fax 620-431-7909 • sales@nuwa.com • www.nuwa.com

DEFECT and NONCOMPLIANCE REPORT

Reference: 10E-035

On August 28, 2010 Suburban Manufacturing Company sent Nu Wa Industries Inc. notice that Suburban was conducting a voluntary recall program for certain sealed burner gas range models that were supplied to Nu Wa Industries Inc. One model of the affected gas range was installed as original equipment in a recreational vehicle manufactured by Nu Wa Industries Inc.

1. Manufacturer's name /address:

The manufacturer of the vehicles covered by the report is:

Nu Wa Industries Inc
3701 Johnson Road
Chanute, Kansas 66720

Neil Ford, President

A handwritten signature in black ink that reads 'Neil Ford'.

Tel: 620-431-2088
Fax: 620-431-7901

Date this report was fill out: September 22, 2010

Report completed by Michael Anderson

2. Vehicles Involved:

The vehicle listed below is the only vehicle that received a sealed burner range with a potential defect. The vehicle was manufactured in 2010. The vehicle make model and year are as follows:

Nu Wa Discovery Series, 2010 model year, VIN 1NW32DR01BD078426

Only vehicles that were equipped with one of the following model of sealed burner ranges are covered by this recall notice.

SRSA3SBBE, SRSA3LBBE, SRSA3LBGE, SRSA3LBSE, SRSA3SPSS and SRSA3LPSS that fall in the serial number range beginning with 094606308 and ending with 102508929. These ranges were shipped from Suburban Manufacturing Company between November 1, 2009 and July 31, 2010.

3. Total number of vehicles:

The total number of vehicles covered by this report is 1.

4. Approximate percentage of vehicles estimated to actually contain the defect:

Based on information supplied by Suburban Manufacturing Company, 100% of the sealed burner ranges received by Nu Wa may contain a potential defect.

5. Description of the defect:

Suburban Manufacturing Company has determined that the possibility exists for the aluminum tube that carries LP gas from the oven control valve to the gas orifice may contain a potential defect which can cause the tube to break. This break in the tubing may result in a gas leak when the oven burner attempts to light causing an LP gas fueled fire inside the range.

6. Chronological summary of events leading to this determination:

Suburban Manufacturing Company advised Nu Wa Industries Inc. of its recall determination by U S mail which was received on August 28, 2010. Suburban records indicated that Nu Wa purchased 1 SRSA3LBBE range that may be under this recall. Nu Wa is not aware of any fires in its vehicles that appear to be related to this defect. Nevertheless, after reviewing the matter Nu Wa has decided to submit this defect report.

7. Program for remedying the defect:

To correct this situation, the gas tube must be replaced before any sale or use of the subject ranges. To confirm that the gas tube has been replaced you can remove the top of the range look in the area between the 3 top burners and find a sticker located above the range's data plate and lighting instructions which says "oven tube replaced".

The only vehicle involved (VIN 1NW32DR01BD078426) in this recall is located at Nu Wa's manufacturing plant at 3701 Johnson Road, Chanute KS 66720. This vehicle will not be sold until the gas tube is replaced and the "oven tube replaced" sticker is put in place. A recall kit has been ordered from Suburban Manufacturing Company and will be installed by Nu Wa's Service Department personal when received.