

GM CUSTOMER CARE AND AFTERSALES
DCS2427
URGENT - DISTRIBUTE IMMEDIATELY

Date: June 25, 2010

Subject: 10023C – Safety Recall
Loss of Power Steering Assist – Replace Electric Power
Steering Motor
Revised Parts Information and Service Procedure
Sections

Models: 2005-2010 Chevrolet Cobalt, 2005 Pontiac Pursuit,
2005-06
Pontiac G4, 2006 Pontiac G5 Pursuit, 2007-10 Pontiac
G5
Equipped with Electric Power Steering

To: All GM Dealers (except Saturn and HUMMER)

Attention: General Manager, Service Manager, Parts Manager,
Used Car Vehicle Manager, and Warranty Administrator

The Parts Information and Service Procedure sections in bulletin 10023C have been revised. Technicians are to review the revised information immediately. Please discard all copies of bulletin 10023B, issue June 2010.

END OF MESSAGE

GM CUSTOMER CARE AND AFTERSALES

Nothing in this message is intended to constitute an electronic signature unless a specific statement to the contrary is included in this message.

Confidentiality Note: This message is intended only for the person or entity to which it is addressed. It may contain confidential and/or privileged material. Any review, transmission, dissemination or other use, or taking of any action in reliance upon this message by persons or entities other than the intended recipient is prohibited and may be unlawful. If you received this message in error, please contact the sender and delete it from your computer.