

GM CUSTOMER CARE AND AFTERSALES

DCS2417

URGENT - DISTRIBUTE IMMEDIATELY

Date: June 15, 2010

Subject: 10088A – Safety Recall  
Hood Louver Separation  
Revised Part Information Section

Models: 2006-10 HUMMER H3; 2009-10 HUMMER H3T

To: All HUMMER Dealers

Attention: General Manager, Service Manager, Parts Manager,  
New Car Vehicle Manager, Used Car Vehicle Manager,  
and  
Warranty Administrator

The Parts Information section in bulletin 10088A has been revised to provide information on obtaining the primer and adhesive needed to complete this recall. Please discard all copies of bulletin 10088, issued April 2010.

END OF MESSAGE

GM CUSTOMER CARE AND AFTERSALES

Nothing in this message is intended to constitute an electronic signature unless a specific statement to the contrary is included in this message.

Confidentiality Note: This message is intended only for the person or entity to which it is addressed. It may contain confidential and/or privileged material. Any review, transmission, dissemination or other use, or taking of any action in reliance upon this message by persons or entities other than the intended recipient is prohibited and may be unlawful. If you received this message in error, please contact the sender and delete it from your computer.