

April 30, 2010

Re: Important Notice – Mandatory fuel shut-off valve upgrade
Bulletin Number: W1-SL-002
Recall Number 10V-165

Dear Valued Westport Customer,

This notice is being sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Reason for this Recall

Westport has decided that a defect related to motor vehicle safety exists in certain Westport ISX G vehicles equipped with Liquefied Natural Gas pumps with the following VIN Numbers:

#	Pump S/N	Vehicle VIN	ESN	Model Year
1	F9624.049	1XKDD49X47R207207	79225579	2007
2	F9624.053	1XKDD49X09R250705	79317720	2009
3	F9624.054	1XKDD49X79J252157	79321600	2009
4	F9624.055	1XKDD49X19R250700	79316782	2009
5	F9624.056	1XKDD49X17R197090	79224978	2007
6	F9624.058	1XKDD49X57R197044	79223875	2007
7	F9624.063	1XKDD49X99R250699	79316191	2009
8	F9624.064	1XKDD49X69R250692	79316189	2009
9	F9624.071	1XKDD49X49J252150	79320736	2009
10	F9624.079	1XKDD49X87R197085	79227791	2007
11	F9624.080	1XKDD49X89J252152	79320734	2009

A vent hole associated with the pump pressure relief valve may have been covered by a welding process, during the manufacture of the pump. This can render the pressure relief valve ineffective, resulting in the possible build up of gas in the pump if the manual shut-off valve is closed. This could result in a sudden leak of high pressure gas within the tank shroud and a slower leak of tank pressure, which could result in personal injury and/or vehicle or property damage.

IMPORTANT NOTE

As described in the Operator's Manual, the manual shut-off valve is open during normal truck operation, and as such you do not need to do anything different during normal vehicle operations. However, it is important to never close the manual shut-off valve while the engine is running as outlined in your ISX G and LNG System Operator's Manual. Please ensure that the manual shutoff valve is open at all times, see Figure 1.




Figure 1: Manual shut-off valve must remain open

What We Will Do

Westport HD will inspect and correct the problem by upgrading to an automatic shut-off valve that does not use the vent hole. The labor time necessary to perform the inspection and service will be approximately 2 hours. Should repair be required, additional time may be necessary. The work will be performed for you at no charge.

What You Should Do

Please contact your Westport Authorized Service dealer, referencing this Notice, to setup a service appointment to perform the necessary work. The contact numbers are:

Inland Kenworth Fontana – 1-909-823-9955 (24-hrs)

Inland Kenworth Montebello – 1-323-278-4100 (24-hrs)

Your Westport dealers are best equipped to obtain parts and provide service to ensure that your vehicle work is completed as promptly as possible. If you have any questions, you can contact Westport directly by calling our toll free hotline at 1-888-WPT-HPDI (1-888-978-4734). If you are unable to obtain service without charge to you and within a reasonable time, you may contact the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE., Washington, DC 20590; or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

If you have changed your address or no longer own the equipment please notify Westport immediately by contacting us at 1-888-WPT-HPDI (1-888-978-4734) or by e-

mail at service@westport.com. Federal law requires that any vehicle lessor receiving this notice must forward a copy of this notice to the lessee within ten days.

We are sorry to cause this inconvenience; however, we have taken this action in the interest of your safety and continued satisfaction with our products. This letter does not constitute an acknowledgment of legal liability.

Thank you for your attention to this matter and we look forward to working with you.

Sincerely,

Westport Field Service Team